

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35087222480000

Completion Report

Spud Date: July 13, 2019

OTC Prod. Unit No.: 087-226165-0-0000

Drilling Finished Date: July 30, 2019

1st Prod Date: December 10, 2019

Completion Date: September 23, 2019

Drill Type: HORIZONTAL HOLE

Well Name: KILKENNY 1-6MH

Purchaser/Measurer: SOUTHWEST

Location: MCCLAIN 6 5N 4W
NW NE NW NW
235 FNL 815 FWL of 1/4 SEC
Latitude: 34.94168869 Longitude: -97.66755113
Derrick Elevation: 1192 Ground Elevation: 1172

First Sales Date: 12/11/2019

Operator: CASILLAS OPERATING LLC 23838

401 S BOSTON AVE STE 2400
TULSA, OK 74103-4060

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	709842		There are no Increased Density records to display.	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9.625	40.00	J-55	1522		375	SURFACE
PRODUCTION	5.5	20.00	P-110CYHP	16914		1205	6529

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 16947

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Dec 14, 2019	MISSISSIPPIAN	640	46	954	1491	763	FLOWING	1719	92/128	1642

Completion and Test Data by Producing Formation			
Formation Name: MISSISSIPPIAN		Code: 359MSSP	Class: OIL
Spacing Orders		Perforated Intervals	
Order No	Unit Size	From	To
698903	640	12014	16806
Acid Volumes		Fracture Treatments	
277 BBLS HCL ACID		320,526 BBLS FLUID 9,940,094 LBS PROPPANT	

Formation	Top
SYCAMORE	11685

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks
There are no Other Remarks.

Lateral Holes
Sec: 6 TWP: 5N RGE: 4W County: MCCLAIN SW SW SE SW 42 FSL 1500 FWL of 1/4 SEC Depth of Deviation: 11539 Radius of Turn: 392 Direction: 178 Total Length: 4792 Measured Total Depth: 16947 True Vertical Depth: 11382 End Pt. Location From Release, Unit or Property Line: 42

FOR COMMISSION USE ONLY	
Status: Accepted	1144691