

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35051247130000

Completion Report

Spud Date: October 07, 2019

OTC Prod. Unit No.: 051-226484-0-0000

Drilling Finished Date: November 20, 2019

1st Prod Date: January 07, 2020

Completion Date: December 22, 2019

Drill Type: HORIZONTAL HOLE

Well Name: JON SNOW 0505 16-9-1WH

Purchaser/Measurer: IRON HORSE

Location: GRADY 16 5N 5W
NW SW NE SW
1729 FSL 1582 FWL of 1/4 SEC
Latitude: 34.90347548 Longitude: -97.73581372
Derrick Elevation: 1043 Ground Elevation: 1018

First Sales Date: 1/8/20

Operator: CAMINO NATURAL RESOURCES LLC 24097

1401 17TH ST STE 1000
DENVER, CO 80202-1247

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	711862		619804	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	13 3/8	54.5	J-55	1513	1130	1064	SURFACE
INTERMEDIATE	9 5/8	40	HCP 110	10533	7900	1387	3765
PRODUCTION	5.5	23	P110 EC	17477	16220	1459	9749

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 17481

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Jan 14, 2020	WOODFORD	197	47	570	2897	2767	FLOWING	1625	30	1050

Completion and Test Data by Producing Formation

Formation Name: WOODFORD

Code: 359WDFD

Class: OIL

Spacing Orders

Order No	Unit Size
702480	640
702481	640
711861	MULTI UNIT

Perforated Intervals

From	To
12927	17243

Acid Volumes

2011 GAL ACID

Fracture Treatments

310,591 BBLS FLUID; 11,557,210 LBS PROP

Formation	Top
WOODFORD	12927

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

There are no Other Remarks.

Lateral Holes

Sec: 9 TWP: 5N RGE: 5W County: GRADY

SW SW SW

388 FSL 410 FWL of 1/4 SEC

Depth of Deviation: 12500 Radius of Turn: 597 Direction: 360 Total Length: 4043

Measured Total Depth: 17481 True Vertical Depth: 13589 End Pt. Location From Release, Unit or Property Line: 388

FOR COMMISSION USE ONLY

Status: Accepted

1144551