

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35137276840000

Completion Report

Spud Date: October 01, 2022

OTC Prod. Unit No.: 137-230692-0-0000

Drilling Finished Date: October 12, 2022

1st Prod Date: January 29, 2023

Completion Date: December 09, 2022

Drill Type: STRAIGHT HOLE

Well Name: TOM 1-16V

Purchaser/Measurer:

Location: STEPHENS 16 3S 4W
SW SE NW NW
1073 FNL 987 FWL of 1/4 SEC
Latitude: 34.300743 Longitude: -97.629788
Derrick Elevation: 0 Ground Elevation: 967

First Sales Date:

Operator: BALCO ENERGY INC 22480

PO BOX 2086
DUNCAN, OK 73534-2086

Completion Type		Location Exception		Increased Density	
	Single Zone		Order No		Order No
	Multiple Zone		0000		0000
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9 5/8	36	J	600		225	SURFACE
PRODUCTION	5 1/2	17	J	5313		80	3300

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 5320

Packer		Plug	
Depth	Brand & Type	Depth	Plug Type
There are no Packer records to display.		There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Jan 29, 2023	MCLISH (BIRDEYE)	13	35			63	PUMPING		open	

Completion and Test Data by Producing Formation			
Formation Name: MCLISH (BIRDEYE)		Code: 202MCLBE	Class: OIL
Spacing Orders		Perforated Intervals	
Order No	Unit Size	From	To
209052	80	5052	5100
Acid Volumes		Fracture Treatments	
33000 GTW 5000 20% HCC		There are no Fracture Treatments records to display.	

Formation	Top
MCLISH (BIRDEYE)	5052
BIRDSEYE	5050
VIOLA	3992

Were open hole logs run? Yes
Date last log run: October 13, 2022

Were unusual drilling circumstances encountered? No
Explanation:

Other Remarks
There are no Other Remarks.

FOR COMMISSION USE ONLY	
Status: Accepted	1149589