Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35049219600001 Completion Report Spud Date: December 11, 2018

OTC Prod. Unit No.: Drilling Finished Date: January 02, 2019

1st Prod Date: June 12, 2019

Amend Reason: RE-ENTRY / CHANGE WELL NAME

Drill Type: STRAIGHT HOLE

Min Gas Allowable: Yes

Well Name: ELK RUN (FERGUSON 10-6) 1-6 Purchaser/Measurer: CIMAREX

Location: GARVIN 6 1N 2W First Sales Date: 06/12/2019

C SW NW SE 1650 FSL 330 FWL of 1/4 SEC

Derrick Elevation: 0 Ground Elevation: 0

Operator: SHAMROCK WELL OPERATIONS LLC 24071

312 S 16TH ST

Amended

FORT SMITH, AR 72901-3834

	Completion Type	Location Exception
Х	Single Zone	Order No
	Multiple Zone	There are no Location Exception records to display.
	Commingled	

Increased Density
Order No
There are no Increased Density records to display.

Casing and Cement										
Type Size Weight Grade Feet PSI SAX Top of CM										
SURFACE	9 5/8	36	K-55	1539		690	SURFACE			
PRODUCTION	5 1/2	17	N-80	11136	2000	1172	9400			

Liner										
Type Size Weight Grade Length PSI SAX Top Depth Bottom Dept										
There are no Liner records to display.										

Total Depth: 11150

Packer						
Depth	Brand & Type					
There are no Packer records to display.						

Plug						
Depth	Plug Type					
There are no Plug records to display.						

	Initial Test Data												
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure			
Jun 12, 2019	HUNTON	10	43	75	7500	2	FLOWING	1400	12/64	30			

September 04, 2019 1 of 2

Completion and Test Data by Producing Formation Class: OIL Formation Name: HUNTON Code: 269HNTN **Spacing Orders Perforated Intervals Order No Unit Size** From То 170515 80 9696 9703 **Acid Volumes Fracture Treatments** NONE 4,000 GALLONS 15%

Formation	Тор
GIBSON	7654
SPRINGER	7900
MISSISSIPPI	8722
UPPER SYCAMORE	9010
LOWER SYCAMORE	9069
WOODFORD	9206
HUNTON	9442
SYLVAN	9706
VIOLA	9949
DENSE BROMIDE	10457
SIMPSON GREEN SHALE	10562
FIRST BROMIDE	10580
SECOND BROMIDE	10713
BASAL BROMIDE	10844
UPPER MCLISH SAND	11010

Were open hole logs run? No Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

RE-ENTRY OF CASILLAS PETROLEUM CORPORATION "FERGUSON 10-6 WELL". DRILLED OUT AND LANDED TUBING @ 9,966', SHOT SQUEEZE HOLES @ 9,830' AND 9,450', SQUEEZED WITH 125 SACKS CEMENT. CEMENT BOND LOG SHOWED GOOD BOND FROM 9,800' - 9,520'. DRILLED OUT SQUEEZE AND MOVED AHEAD WITH COMPLETING HUNTON PER INFORMATION ON FORM. ALL SURACE AND PRODUCTION CASING INFORMATION AND FORMATION TOPS ARE FROM ORIGINAL 1002A.

FOR COMMISSION USE ONLY

1143297

Status: Accepted

September 04, 2019 2 of 2

NAME (PRINT OR TYPE)

72901

ZIP

AR

STATE

Fort Smith

CITY

SIGNATURE

312 South 16th Street

ADDRESS

Form 1002A

PHONE NUMBER

DATE

pshields@shieldsfs.com

EMAIL ADDRESS

Rev 2009

PLEASE TYPE OR USE BLACK INK ONLY


FORMATION RECORD

Give formation names and tops, if available, or descriptions and thickness of formations drilled through. Show intervals cored or drillstem tested.

NAMES OF FORMATIONS	TOP
Gibson	7,654
Springer	7,900
Mississippi	8722
Upper Sycamore	9,010
Lower Sycamore	9,069
Woodford	9,206
Hunton	9,442
Sylvan	9,706
Viola	9,949
Dense Bromide	10,457
Simpson Green Shale	10,562
First Bromide	10,580
2nd Bromide	10,713
Basal Bromide	10,844
Upper McLish Sd	11,010

LEASE NAME	WELL NO
	FOR COMMISSION USE ONLY
ITD on file YES APPROVED DISAPPROVED	NO 2) Reject Codes
Were open hole logs run? Date Last log was run	_yes _ <u>X</u> _no
Was CO ₂ encountered?	yes X no at what depths?
Was H ₂ S encountered? Were unusual drilling circumstances encoulf yes, briefly explain below	yesX_ no at what depths?yesX_ no


Other remarks: Re-entry of Casillas Petroleum Corporation "Ferguson #10-6 Well". Drilled out & landed tbg @ 9,966', shot squeeze holes @ 9,830' & 9,450', squeezed w/ 125 sks cmt. CBL showed good bond from 9,800-9,520'. Drilled out squeeze & moved ahead w/ completing Hunton per info on form. All surface and production casing information and formation tops are from original 1002A.



If more than three drainholes are proposed, attach a separate sheet indicating the necessary information.

Direction must be stated in degrees azimuth. Please note, the horizontal drainhole and its end point must be located within the boundaries of the lease or spacing unit.

Directional surveys are required for all drainholes and directional wells.



BOTTOM HOLE LOCATION FOR DIRECTIONAL HOLE

SEC	TWP	RGE		COUNTY			
Spot Locati	on 1/4	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Measured 7			Vertical De		BHL From Lease, Unit, or Prope	rty Line:	

BOTTOM HOLE LOCATION FOR HORIZONTAL HOLE: (LATERALS)

LATERAL #1

SEC	TWP	RGE		COUNTY			
Spot Locati	on 1/4	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Depth of Deviation			Radius of Turn		Direction	Total Length	
Measured 1	Total Depth		True Vertical De	pth	BHL From Lease, Unit, or Prope	rty Line:	

SEC	TWP	RGE		COUNTY				
Spot Loc	cation 1/4	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL		FWL
Depth of Deviation	f		Radius of Turn		Direction	Total Length		
Measured Total Depth True Vertical Dep			pth	BHL From Lease, Unit, or Property Line:				

Spot Location		1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Depth of Radius of Turn Deviation			Direction BHL From Lease, Unit, or Pro	Total Length		