

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35051247370000

Completion Report

Spud Date: December 10, 2019

OTC Prod. Unit No.: 051-226611-0-0000

Drilling Finished Date: December 30, 2019

1st Prod Date: February 25, 2020

Completion Date: February 17, 2020

Drill Type: HORIZONTAL HOLE

Well Name: SAM NOBLE 0907 2-11 1MXH

Purchaser/Measurer: IRON HORSE

Location: GRADY 2 9N 7W
SE NE NE NE
340 FNL 265 FEL of 1/4 SEC
Latitude: 35.28971174 Longitude: -97.90117977
Derrick Elevation: 1361 Ground Elevation: 1338

First Sales Date: 2/25/20

Operator: CAMINO NATURAL RESOURCES LLC 24097

1401 17TH ST STE 1000
DENVER, CO 80202-1247

Completion Type	
X	Single Zone
	Multiple Zone
	Commingled

Location Exception	
Order No	
712124	

Increased Density	
Order No	
There are no Increased Density records to display.	

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9.625	36	J55	1506	2020	496	SURFACE
PRODUCTION	5.5	20	P110EC	21438	11100	3096	SURFACE

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 21438

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Mar 16, 2020	MISSISSIPPI LIME	200	47	2681	13405	4620	FLOWING	1242	50	768

Completion and Test Data by Producing Formation

Formation Name: MISSISSIPPI LIME

Code: 351MSSLM

Class: OIL

Spacing Orders

Order No	Unit Size
319301	
328394	
712123	MULTI UNIT

Perforated Intervals

From	To
11293	21377

Acid Volumes

758 GAL ACID

Fracture Treatments

563,315 BBLs FLUID; 25,771,020 LBS PROP

Formation	Top
MISSISSIPPI LIME	11106

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

There are no Other Remarks.

Lateral Holes

Sec: 11 TWP: 9N RGE: 7W County: GRADY

SE SE SE SE

106 FSL 340 FEL of 1/4 SEC

Depth of Deviation: 10509 Radius of Turn: 619 Direction: 175 Total Length: 9957

Measured Total Depth: 21438 True Vertical Depth: 11409 End Pt. Location From Release, Unit or Property Line: 106

FOR COMMISSION USE ONLY

1145194

Status: Accepted