

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35087221070001

Completion Report

Spud Date: March 05, 2018

OTC Prod. Unit No.: 087-223883-0-0000

Drilling Finished Date: May 10, 2018

1st Prod Date: July 19, 2018

Completion Date: July 13, 2018

Drill Type: HORIZONTAL HOLE

Min Gas Allowable: Yes

Well Name: JUNE 1H-19

Purchaser/Measurer: ENABLE GATHERING AND
PROCESSING

First Sales Date: 7/19/2018

Location: MCCLAIN 18 8N 4W
SW SW SW SE
320 FSL 2390 FEL of 1/4 SEC
Latitude: 35.161187 Longitude: -97.660794
Derrick Elevation: 1279 Ground Elevation: 1255

Operator: NEWFIELD EXPLORATION MID-CON INC 20944

4 WATERWAY AVE STE 100
THE WOODLANDS, TX 77380-2764

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	688965		There are no Increased Density records to display.	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9.625	36	J-55	1474		380	SURFACE
PRODUCTION	5.5	20	P-110	14774		2142	500

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 14774

Packer		Plug	
Depth	Brand & Type	Depth	Plug Type
There are no Packer records to display.		There are no Plug records to display.	

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Jul 29, 2018	WOODFORD	250	40	152	608	2536	FLOWING	1010	64	2626

Completion and Test Data by Producing Formation

Formation Name: WOODFORD

Code: 319WDFD

Class: OIL

Spacing Orders

Order No	Unit Size
672580	640

Perforated Intervals

From	To
10148	14672

Acid Volumes

15% HCL = 644 BBLS.

Fracture Treatments

TOTAL FLUIDS = 151,262 BBLS TOTAL PROPPANT = 5,512,560 LBS

Formation	Top
WOODFORD	9880

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

There are no Other Remarks.

Lateral Holes

Sec: 19 TWP: 8N RGE: 4W County: MCCLAIN

SE SE SW SE

355 FSL 1349 FEL of 1/4 SEC

Depth of Deviation: 9606 Radius of Turn: 573 Direction: 177 Total Length: 10023

Measured Total Depth: 14774 True Vertical Depth: 10023 End Pt. Location From Release, Unit or Property Line: 355

FOR COMMISSION USE ONLY

1140452

Status: Accepted