Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35063246750001 **Completion Report** Spud Date: June 12, 2017

OTC Prod. Unit No.: 063-225237-0-0000 Drilling Finished Date: October 29, 2018

1st Prod Date: March 05, 2019

Completion Date: January 23, 2019

Drill Type: **HORIZONTAL HOLE**

Min Gas Allowable: Yes

Well Name: ANDERSON EAST 1-2/35H Purchaser/Measurer: MARKWEST

Location: HUGHES 10 8N 11E First Sales Date: 03/05/2019

SE NE NE NE

610 FNL 210 FEL of 1/4 SEC

Latitude: 35.186806 Longitude: -96.1242872 Derrick Elevation: 869 Ground Elevation: 846

Operator: BRAVO ARKOMA LLC 23562

> 1323 E 71ST ST STE 400 TULSA, OK 74136-5067

	Completion Type
Х	Single Zone
	Multiple Zone
	Commingled

Location Exception
Order No
666673

Increased Density
Order No
660067

		Cas	sing and Ceme	ent			
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
CONDUCTOR	20			40			SURFACE
SURFACE	9 5/8	40	J-55	1123		435	SURFACE
PRODUCTION	5 1/2	20	P-110	15977		2230	2855

				Liner				
Туре	Type Size Weight Grade Length PSI SAX Top Depth Bottom Depth							
			There are	no Liner record	ds to displa	ay.		

Total Depth: 16000

Pac	ker			
Depth Brand & Type				
There are no Packe	r records to display.			

Plug					
Depth	Plug Type				
There are no Plug	records to display.				

Initial Test Data

June 19, 2019 1 of 2

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Apr 05, 2019	WOODFORD			2890		649	FLOWING	308	128/64	130

Completion and Test Data by Producing Formation

Formation Name: WOODFORD

Code: 319WDFD

Class: GAS

Spacing Orders				
Order No	Unit Size			
530078	640			
665769	640			
667287	MULTIUNIT			

Perforated Intervals			
From	То		
5792	15874		

Acid Volumes
66,036 GALLONS 15% HCL

Fracture Treatments
360,797 BARRELS FRAC FLUID, 11,770,884 POUNDS 40/70 SAND

Formation	Тор
WOODFORD	4577

Were open hole logs run? No Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

OCC - THIS DOCUMENT IS ACCEPTED BASED ON THE DATA SUBMITTED NEITHER THE FINAL LOCATION EXCEPTION NOR THE FINAL MULTIUNIT ORDERS HAVE BEEN SUBMITTED.

Lateral Holes

Sec: 35 TWP: 9N RGE: 11E County: HUGHES

NE NE NE NW

169 FNL 2492 FWL of 1/4 SEC

Depth of Deviation: 4445 Radius of Turn: 629 Direction: 2 Total Length: 11360

Measured Total Depth: 16000 True Vertical Depth: 4519 End Pt. Location From Release, Unit or Property Line: 169

FOR COMMISSION USE ONLY

1142802

Status: Accepted

June 19, 2019 2 of 2

NAME (PRINT OR TYPE)

OK

STATE

Tulsa

CITY

74136

ZIP

SIGNATURE

1323 East 71st St, Suite 400

ADDRESS

Form 1002A

Rev. 2009

PHONE NUMBER

DATE

tharold@bravonr.com

EMAIL ADDRESS

PLEASE TYPE OR USE BLACK INK ONLY

FORMATION RECORD Give formation names and tops, if available, or descriptions and thickness of formations drilled through. Show intervals cored or drillstem tested.		LEASE NAME	Anderson East	WELL NO	1-2/35H
NAMES OF FORMATIONS	TOP		FOR COMMISSION	ON USE ONLY	

drilled through. Show intervals cored or drillstem tes	ited.			
NAMES OF FORMATIONS	TOP		FOR COMMISSION U	SE ONLY
Woodford	4,577	ITD on file YES	NO	
		APPROVED DISAPI	PROVED 2) Reject Codes	
1				
23				
•				
		Were open hole logs run?	yes X no	
		Date Last log was run		
			X	
		Was CO ₂ encountered?		at depths?
		Was H₂S encountered?	yes _X no at wha	t depths?
		Were unusual drilling circumst	ances encountered?	yesX no
		If yes, briefly explain below		
Other remarks:				
	a la company			
C40 A				
640 Acres	BOTTOM HOLE LOCATION FOR	DIRECTIONAL HOLE		
	SEC TWP RO	GE COUNTY		
	Spot Location	For	et From 1/4 Sec Lines FSL	FWL
	1/4 1/4 Measured Total Depth	1/4 1/4	et From 1/4 Sec Lines FSL IL From Lease, Unit, or Property Line:	- FVVL
	Measured Total Deptil	True vertical Deptit	L From Lease, Oriit, or Froperty Line.	
	BOTTOM HOLE LOCATION FOR	HORIZONTAL HOLE: (LATERALS)		
	LATERAL #1			
	SEC 35 TWP 09N RO	GE 11E COUNTY	HUGHE	S
	Spot Location			
	NE 1/4 NE 1/4	INC 1/4 INVV 1/4	et From 1/4 Sec Lines FNL	169 FWL 2492
If more than three drainholes are proposed, attach a	Depth of 4,445	Radius of Turn 629	rection 2 Total Length	11,360
separate sheet indicating the necessary information.	Measured Total Depth	True Vertical Depth BH	IL From Lease, Unit, or Property Line:	
Direction must be stated in degrees azimuth.	16,000	4,519	169	
Please note, the horizontal drainhole and its end	LATERAL NO			
point must be located within the boundaries of the lease or spacing unit.	SEC TWP RO	GE COUNTY		
Directional surveys are required for all				
drainholes and directional wells.	Spot Location 1/4 1/4	1/4 1/4 Fee	et From 1/4 Sec Lines FSL	FWL
640 Acres	Depth of	Radius of Turn Dire	rection Total	
	Deviation Measured Total Depth	True Vertical Depth BH	Length IL From Lease, Unit, or Property Line:	
	SEC TWP RO	GE COUNTY		
		COUNTY		
	Spot Location 1/4 1/4	1/4 1/4 Fee	et From 1/4 Sec Lines FSL	FWL
	Depth of		rection Total	
	Deviation Measured Total Depth	True Vertical Depth BH	Length IL From Lease, Unit, or Property Line:	<u> </u>

smag- willer.

BNR Well Location Plat As-Drilled

SECTION LINE 3

LOT 3

2

LAST PERF

197' FSL - 1999' FWL MD: 5792' TVD: 4601'

BOTTOM HOLE LOC. 169' FNL - 2492' FWL MD: 16000'

TVD: 4519

FIRST PERF: 295' FNL - 2483' FWL MD: 15874'

LOT 2

TVD: 4519

X:256603

X:2565859 Y:685676

X:2565959 Y:680413

LOT 1

S.H.L. Sec. 10-8N-11E I.M. B.H.L. Sec. 35-9N-11E I.M.

Operator: BRAVO NATURAL RESOURCES Lease Name and No.: ANDERSON EAST 1-2/35H

Footage : 610' FNL - 210' FEL GR. ELEVATION: 846' Good Site? YES

:690875

LOT 4

SECTION LINE

1981' FWL MD: 5594' TVD: 4592

SECTION LINE 1: 600' FSL MD: 2024' TVD: 1992'

Section: 10 Township: 8N Range: 11E

County: Hughes State of Oklahoma Terrain at Loc.: Location fell in open field.

X:2560578 Y:685581

X:2560676 Y:680341

on was staked on the gravey is not guaranteed. F d. GPS data is observed n hereon for Section Cor Boundary Survey.

Quarter Section distances may be as opposing section comers, or occupal represent a true boundary survey. The section of the s



1"=1500 **GPS DATUM** NAD 27

OK SOUTH ZONE

Surface Hole Loc.: Lat: 35°11'12.50"N Lon: 96°07'27.43"W Lat: 35.18680604 Lon: -96.12428720 X: 2560474 Y: 679726

Section Crossing 1: Lat: 35°11'12.50"N Lon: 96°07'27.43"W Lat: 35.18683569 Lon: -96.12358429 X: 2560684 Y: 679740

Section Crossing 2: Lat: 35°11'18.45"N Lon: 96°07'01.00"W Lat: 35.18845773 Lon: -96.11694391 X: 2562657 Y: 680368

X:2566145

Last Perf: Lat: 35°11'20.40"N Lon: 96°07'00.78"W Lat: 35.18899902 Lon: -96.11688347 X: 2562672 Y: 680565

Section Crossing 3: Lat: 35°12'10.37"N Lon: 96°06'56.40"W Lat: 35.20288112 Lon: -96.11566771 X: 2562940 Y: 685624

First Perf: Lat: 35°12'59.71"N Lon: 96°06'51.74"W Lat: 35.21658504 Lon: -96.11437350 X: 2563234 Y: 690618

Bottom Hole Loc.: Lat: 35°13'00.95"N Lon: 96°06'51.65"W Lat: 35.21693047 Lon: -96.11434594 X: 2563240 Y: 690744

Arkoma Surveying and Mapping, PLLC P.O. Box 238 Wilburton, OK 74578 Ph. 918-465-5711 Fax 918-465-5030 Certificate of Authorization No. 5348 Expires June 30, 2020


Invoice #7156-A-AD Date Staked : 05/26/17 Date Drawn : 06/09/17 Date Drawn: 06/09/17 By: R.S. Add As-Drilled: 06/15/17 By: S.S. Added Perfs: 12/19/18 By: R.S./S.S.

Certification:

This is to certify that this Well Location Plat represents the results of a survey made on the ground performed under the supervision of the undersigned.



12/19/18



PLEASE TYPE OR USE BLACK INK ONLY

$\Delta TI \cap NI$	RECORD

Give formation names and tops, if available, or descriptions and thickness of formations drilled through. Show intervals cored or drillstem tested.

Woodford	4,577		ITD on file	YES		COOMMISSION SOL	, , , , , , , , , , , , , , , , , , ,
			APPROVED	DIS	APPROVED	2) Reject Codes	
•					,		
			Word onen bo	olo logo puo?	Voc	V 20	
			Were open ho	_	yes	X_ no	
			Date Last log			X	
			Was CO₂ enc	countered?			pths?
			Was H₂S enco	ountered?	yes	no at what de	pths?
			Were unusual If yes, briefly e		mstances encountered	1?	yes _X _no
Other remarks:					Д.		
·							
640 Acres	BOTTOM HOLE LOCATION F	OR DIREC	CTIONAL HOLE				
	SEC TWP	RGE	cc	DUNTY			
	Spot Location 1/4	1/4	1/4	1/4	Feet From 1/4 Sec Lin	nes FSL	FWL
	Measured Total Depth		e Vertical Depth		BHL From Lease, Uni	t, or Property Line:	
	4						~~~
	BOTTOM HOLE LOCATION F	OR HORIZ	ZONTAL HOLE:	(LATERALS	6)		
	LATERAL #1						
	SEC 35 TWP 09N	RGE	11E CC	DUNTY		HUGHES	
	Spot Location NE 1/4 NE	1/4	NE 1/4	NW 1/4	Feet From 1/4 Sec Lin	nes FNL 1	69 FWL 2492
If more than these desimbles are presented attached	Depth of 4 445		dius of Turn	629	Direction	2 Total	11,360
If more than three drainholes are proposed, attach a separate sheet indicating the necessary information.	Deviation 7,445 Measured Total Depth	Ţru	e Vertical Depth		BHL From Lease, Uni	Length it, or Property Line:	<u> </u>
	16,000		4 - 4 0				
Direction must be stated in degrees azimuth.	16,000		4,519)		169	
Direction must be stated in degrees azimuth. Please note, the horizontal drainhole and its end point must be located within the boundaries of the	LATERAL #2					169	
Please note, the horizontal drainhole and its end point must be located within the boundaries of the lease or spacing unit.		RGE		OUNTY	· · · · · · · · · · · · · · · · · · ·	169	
Please note, the horizontal drainhole and its end point must be located within the boundaries of the lease or spacing unit. Directional surveys are required for all	LATERAL #2 SEC TWP Spot Location		cc	DUNTY	Feet From 1/4 Sec Lin		FWL
Please note, the horizontal drainhole and its end point must be located within the boundaries of the lease or spacing unit.	LATERAL #2 SEC TWP Spot Location 1/4 Depth of	1/4			Feet From 1/4 Sec Lin	nes FSL Total	FWL
Please note, the horizontal drainhole and its end point must be located within the boundaries of the lease or spacing unit. Directional surveys are required for all drainholes and directional wells.	LATERAL #2 SEC TWP Spot Location 1/4	1/4 Rad	1/4	DUNTY 1/4		nes FSL Total Length	FWL
Please note, the horizontal drainhole and its end point must be located within the boundaries of the lease or spacing unit. Directional surveys are required for all drainholes and directional wells.	LATERAL #2 SEC TWP Spot Location 1/4 Depth of Deviation	1/4 Rad	1/4 dius of Turn	DUNTY 1/4	Direction	nes FSL Total Length	FWL
Please note, the horizontal drainhole and its end point must be located within the boundaries of the lease or spacing unit. Directional surveys are required for all drainholes and directional wells.	SEC TWP Spot Location 1/4 Depth of Deviation Measured Total Depth	1/4 Rac	1/4 dius of Turn le Vertical Depth	DUNTY 1/4	Direction	nes FSL Total Length	FWL
Please note, the horizontal drainhole and its end point must be located within the boundaries of the lease or spacing unit. Directional surveys are required for all drainholes and directional wells.	Sec TWP Spot Location 1/4 Depth of Deviation Measured Total Depth	1/4 Rad	1/4 dius of Turn le Vertical Depth	DUNTY 1/4	Direction	nes FSL Total Length	FWL
Please note, the horizontal drainhole and its end point must be located within the boundaries of the lease or spacing unit. Directional surveys are required for all drainholes and directional wells.	LATERAL #2 SEC TWP Spot Location 1/4 Depth of Deviation Measured Total Depth LATERAL #3 SEC TWP Spot Location	1/4 Rac	1/4 dius of Turn le Vertical Depth	DUNTY 1/4	Direction	rotal Length it, or Property Line:	FWL
Please note, the horizontal drainhole and its end point must be located within the boundaries of the lease or spacing unit. Directional surveys are required for all drainholes and directional wells.	SEC TWP Spot Location 1/4 Depth of Deviation Measured Total Depth LATERAL #3 SEC TWP	1/4 Rac	1/4 dius of Turn le Vertical Depth	DUNTY 1/4	Direction BHL From Lease, Uni	rotal Length it, or Property Line:	

LEASE NAME

WELL NO. __1-2/35H

Anderson East