Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000 Rule 165: 10-3-25

API No.: 35151245740000 Completion Report Spud Date: September 01, 2019

OTC Prod. Unit No.: 151-226257-0-0000 Drilling Finished Date: September 10, 2019

1st Prod Date: September 25, 2019

Completion Date: September 18, 2019

Drill Type: HORIZONTAL HOLE

Well Name: SNYDER 14-29-14 1H Purchaser/Measurer: TARGA

Location: WOODS 14 29N 14W

SE SE SW SE

180 FSL 1535 FEL of 1/4 SEC

Latitude: 36.986633599 Longitude: -98.675995036 Derrick Elevation: 1414 Ground Elevation: 1396

Operator: BCE-MACH LLC 24174

14201 WIRELESS WAY STE 300 OKLAHOMA CITY, OK 73134-2512

Completion Type								
Х	Single Zone							
Multiple Zone								
	Commingled							

Location Exception					
Order No					
699870					

Increased Density						
Order No						
There are no Increased Density records to display.						

First Sales Date: 09/25/2019

Casing and Cement								
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT	
SURFACE	13.375	48	J-55	424		175	SURFACE	
INTERMEDIATE	7	26	P-110	5325		220	2645	

Liner										
Туре	pe Size Weight Grade Length PSI SAX				SAX	Top Depth	Bottom Depth			
LINER	4.5	11.6	P-110	P-110 4051		0	5224	9275		

Total Depth: 9282

Packer						
Depth	Brand & Type					
4906	AS1X					

Plug						
Depth Plug Type						
There are no Plug records to display.						

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Oct 13, 2019	MISSISSIPPIAN	14	20	30	2142	2427	GASLIFT		128	120

March 10, 2020 1 of 2

Completion and Test Data by Producing Formation Formation Name: MISSISSIPPIAN Code: 359MSSP Class: OIL **Spacing Orders Perforated Intervals Order No Unit Size** From То 692784 640 5325 9282 **Acid Volumes Fracture Treatments** 214 BBLS 15% HCL 29611 BBLS / 0 LBS SAND

Formation	Тор
MISSISSIPPIAN	4888

Were open hole logs run? No Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

OH PACKER/SLEEVE SYSTEM.

Lateral Holes

Sec: 14 TWP: 29N RGE: 14W County: WOODS

SE SW SE SE

50 FNL 699 FEL of 1/4 SEC

Depth of Deviation: 4418 Radius of Turn: 578 Direction: 359 Total Length: 3957

Measured Total Depth: 9282 True Vertical Depth: 4914 End Pt. Location From Release, Unit or Property Line: 50

FOR COMMISSION USE ONLY

1144021

Status: Accepted

March 10, 2020 2 of 2