

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35045238270000

Completion Report

Spud Date: March 07, 2020

OTC Prod. Unit No.: 045-227056 / 129-227056

Drilling Finished Date: March 25, 2020

1st Prod Date: November 23, 2020

Completion Date: October 21, 2020

Drill Type: HORIZONTAL HOLE

Well Name: PARKER 23X26-18-25C 3H

Purchaser/Measurer:

Location: ELLIS 14 18N 25W
NE SW SE SW
350 FSL 1765 FWL of 1/4 SEC
Latitude: 36.02876592 Longitude: -99.839368013
Derrick Elevation: 2175 Ground Elevation: 2157

First Sales Date:

Operator: UNBRIDLED RESOURCES LLC 23429

1111 BAGBY ST STE 1600
HOUSTON, TX 77002

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	716389		705595	
	Commingled			706545	

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9 5/8	36	J-55	515		344	SURFACE
INTERMEDIATE	7	29	P-110 CY	8634		490	SURFACE
PRODUCTION	4 1/2	13.5	P-110	19732		755	8362

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 19744

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Jan 11, 2021		331	46	619	1.87	958	FLOWING	548	54	169

Completion and Test Data by Producing Formation

Formation Name: CLEVELAND

Code: 405CLVD

Class: OIL

Spacing Orders

Order No	Unit Size
100886	640
716388	MULTI UNIT

Perforated Intervals

From	To
9630	19589

Acid Volumes

2,343 BBL – 15% HCL

Fracture Treatments

10,849,584 LBS REGIONAL SAND 2,508,050 LBS RCS SAND 300,848 BBL WATER

Formation	Top
CLEVELAND	8929

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

There are no Other Remarks.

Lateral Holes

Sec: 14 TWP: 18N RGE: 25W County: ROGER MILLS

NE SW SE SW

24 FSL 1782 FEL of 1/4 SEC

Depth of Deviation: 8787 Radius of Turn: 522 Direction: 177 Total Length: 10108

Measured Total Depth: 19744 True Vertical Depth: 7176 End Pt. Location From Release, Unit or Property Line: 24

FOR COMMISSION USE ONLY

1146277

Status: Accepted