

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35049252220000

Completion Report

Spud Date: December 21, 2018

OTC Prod. Unit No.:

Drilling Finished Date: January 06, 2019

1st Prod Date:

Completion Date: January 06, 2019

Drill Type: STRAIGHT HOLE

Well Name: DONNA 1-7

Purchaser/Measurer:

Location: GARVIN 7 3N 2W
NW SE NE SE
1942 FSL 498 FEL of 1/4 SEC
Latitude: 34.744352 Longitude: -97.441892
Derrick Elevation: 962 Ground Elevation: 946

First Sales Date:

Operator: RANKEN ENERGY CORPORATION 17205

457 W 18TH ST
EDMOND, OK 73013-3663

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	There are no Location Exception records to display.		There are no Increased Density records to display.	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	8-5/8"	32#	J-55 LT&C	317		270	SURFACE

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 8350

Packer		Plug	
Depth	Brand & Type	Depth	Plug Type
There are no Packer records to display.		360	CEMENT

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
There are no Initial Data records to display.										
Completion and Test Data by Producing Formation										

Formation Name: NONE

Code:

Class: PLUG AND ABANDON

Formation	Top
HOGSHOOTER LIME	5327
CHECKERBOARD LIME	5619
1ST DEESE SAND	5768
2ND DEESE SAND	6028
3RD DEESE SAND	6344
BASAL PANNE / SYLVAN SHALE	6410
VIOLA LIMESTONE	6457
BROMIDE DENSE LIME	6932
1ST BROMIDE SAND	7064
2ND BROMIDE SAND	7218
3RD BROMIDE SAND (TULIP CREEK)	7321
MCLISH SAND	7507
OIL CREEK SHALE	7866
BASAL OIL CREEK SAND	8236
JOINS FORMATION	8314

Were open hole logs run? Yes

Date last log run: January 05, 2019

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

OCC - DRY HOLE WELL PLUGGED 1/6/19

FOR COMMISSION USE ONLY

1141947

Status: Accepted