

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35125239630000

Completion Report

Spud Date: June 11, 2022

OTC Prod. Unit No.:

Drilling Finished Date: June 19, 2022

1st Prod Date:

Completion Date: August 18, 2022

Drill Type: STRAIGHT HOLE

Min Gas Allowable: Yes

Well Name: COHESIVE 1-1

Purchaser/Measurer:

Location: POTTAWATOMIE 1 10N 4E
SW SW SW NW
2475 FNL 290 FWL of 1/4 SEC
Latitude: 35.369645 Longitude: -96.840116
Derrick Elevation: 0 Ground Elevation: 962

First Sales Date:

Operator: GLB EXPLORATION INC 18634

7716 MELROSE LANE
OKLAHOMA CITY, OK 73127-6002

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	724784		There are no Increased Density records to display.	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9 5/8	36	J-55	1368		225	SURFACE
PRODUCTION	5.5	17	N-80	5028		225	4000

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 5120

Packer		Plug	
Depth	Brand & Type	Depth	Plug Type
4784.36	MODEL R PACKER 5.5 X 2 7/8	There are no Plug records to display.	

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Aug 11, 2022	VIOLA					142	SWAB		0	

Completion and Test Data by Producing Formation

Formation Name: VIOLA

Code: 202VIOL

Class: DRY

Spacing Orders

Order No	Unit Size
724437	

Perforated Intervals

From	To
4820	4860

Acid Volumes

95 BARRELS 15%NEFE HCl ACID

Fracture Treatments

3,000 BARRELS 4% KCL WATER 69,000 POUNDS 40/70 MESH SAND 16,500 POUNDS 40/70 MESH RESIN SAND
--

Formation	Top
EARLSBORO	4070
MISSISSIPPI	4465
WOODFORD	4617
SYLVAN	4726
VIOLA	4860
VIOLA TRENTON	4872
1ST WILCOX	4898
2ND WILCOX	4987

Were open hole logs run? Yes

Date last log run: June 27, 2022

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

OCC - OPERATOR WAS WARNED THAT THE TESTING THE VIOLA WITHOUT APPROVAL ON A PERMIT TO DRILL WAS A RULE VIOLATION.

FOR COMMISSION USE ONLY

1148903

Status: Accepted