Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35049245720001 **Completion Report** Spud Date: September 30, 2006

OTC Prod. Unit No.: Drilling Finished Date: November 30, 2006

1st Prod Date: April 01, 2007

Completion Date: December 28, 2006 Amend Reason: RECOMPLETION TO HUNTON

Recomplete Date: May 08, 2018

First Sales Date:

Drill Type: **DIRECTIONAL HOLE**

Amended

Min Gas Allowable: Yes

Well Name: TAMMY 1 Purchaser/Measurer:

GARVIN 36 1N 1E Location:

SE NE SW 932 FSL 2437 FWL of 1/4 SEC

Latitude: 34.5090835 Longitude: -97.1516104

Derrick Elevation: 816 Ground Elevation: 797

Operator: BAYS EXPLORATION INC 18082

> 4005 NW EXPRESSWAY STE 600 OKLAHOMA CITY, OK 73116-1689

Completion Type					
Х	Single Zone				
	Multiple Zone				
	Commingled				

Location Exception
Order No
There are no Location Exception records to display.

Increased Density
Order No
There are no Increased Density records to display.

Casing and Cement							
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
CONDUCTOR	16	65	H40	46		140	SURFACE
SURFACE	13 3/8	54.5	J55	235		135	SURFACE
INTERMEDIATE	9 5/8	40	K55	3414		1100	SURFACE
PRODUCTION	5.5	17	L80	9849		950	5050

				Liner				
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 9866

Packer					
Depth Brand & Type					
There are no Packer records to display.					

Plug					
Depth	Plug Type				
8040	CIBP				
7390	CIBP				

March 23, 2021 1 of 3

	Initial Test Data									
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
May 10, 2018	HUNTON	12	34.4	70	5833	23	PUMPING			
Mar 14, 2021	HUNTON	2	34.4	10	5000		PUMPING		0	

Completion and Test Data by Producing Formation

Formation Name: HUNTON

Code: 269HNTN

Class: OIL

Spacing Orders					
Order No	Unit Size				
484491	80				

Perforated Intervals				
From	То			
6964	6974			
7000	7020			

Acid Volumes

4,000 GALS 15% HCL 19,000 10% HCL

Fracture Treatments

FRAC WITH 4,000 GALS 15% NEFE HCL, 137,000 GALS 1.5% HCL SLICKWATER, 10,000 GALS SLICKWATER FLUSH AND 45,000 POUNDS 30/50 SAND

Formation	Тор
DEESE	3530
SPRINGER	4140
CANEY	6038
SYCAMORE	6470
WOODFORD	6895
HUNTON	6970
SYLVAN	7215
VIOLA	7435
BROMIDE	8022
MCLISH	8775
OIL CREEK	9385
ARBUCKLE	9772

Were open hole logs run? Yes Date last log run: November 17, 2006

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

1002A MIGRATION

OCC - RECOMPLETION TO HUNTON. THE VIOLA PERFORATIONS ARE BELOW CAST IRON BRIDGE PLUG AT 7,390'

Bottom Holes

March 23, 2021 2 of 3 Sec: 36 TWP: 1N RGE: 1E County: GARVIN

SW SE

585 FSL 783 FWL of 1/4 SEC

Depth of Deviation: 0 Radius of Turn: 0 Direction: 0 Total Length: 0

Measured Total Depth: 9856 True Vertical Depth: 9792 End Pt. Location From Release, Unit or Property Line: 585

FOR COMMISSION USE ONLY

1145679

Status: Accepted

March 23, 2021 3 of 3