

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35051244840000

Completion Report

Spud Date: October 01, 2018

OTC Prod. Unit No.: NA

Drilling Finished Date: October 12, 2018

1st Prod Date:

Completion Date: November 26, 2018

Drill Type: STRAIGHT HOLE

Well Name: JC NELSON 1-16-9HM

Purchaser/Measurer:

Location: GRADY 16 8N 7W
SW SE SE SE
329 FSL 338 FEL of 1/4 SEC
Latitude: 35.161129 Longitude: -97.936153
Derrick Elevation: 1183 Ground Elevation: 1156

First Sales Date:

Operator: CONTINENTAL RESOURCES INC 3186
PO BOX 269000
20 N BROADWAY AVE
OKLAHOMA CITY, OK 73126-9000

Completion Type		Location Exception		Increased Density	
	Single Zone	Order No		Order No	
	Multiple Zone	There are no Location Exception records to display.		There are no Increased Density records to display.	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9 5/8	40	J-55	1472		450	SURFACE

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 12293

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
6150	CEMENT
2950	CEMENT
1572	CEMENT
420	CEMENT
34	CEMENT

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
-----------	-----------	----------------	----------------------	----------------	----------------------------	------------------	----------------------	---------------------------------	---------------	-------------------------

There are no Initial Data records to display.

Completion and Test Data by Producing Formation

Formation Name: NONE

Code:

Class: PLUG AND ABANDON

Formation	Top
-----------	-----

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? Yes

Explanation: PROBLEMS WITH HIGH GAS, HOLE PACKING OFF, DRILL STRING PARTED WHILE TRYING TO TRIP OUT OF HOLE. TOP OF FISH AT 7300'.

Other Remarks

There are no Other Remarks.

FOR COMMISSION USE ONLY

1141470

Status: Accepted