Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000 Rule 165: 10-3-25

Completion Report

API No.: 35047248330001

OTC Prod. Unit No.:

Amended

Amend Reason: RECOMPLETION JOB: FROM ARBURKLE TO WILCOX

Drill Type: DIRECTIONAL HOLE

Well Name: CAROLYN 27-1 SWD

Location: GARFIELD 27 20N 5W SE SW SW SW 135 FSL 495 FWL of 1/4 SEC Latitude: 36.1744325 Longitude: -97.727405 Derrick Elevation: 1014 Ground Elevation: 997

Operator: SK NEMAHA LLC 24221

11700 KATY FWY STE 900 HOUSTON, TX 77079--1222 Spud Date: July 13, 2014

Drilling Finished Date: August 20, 2014

1st Prod Date:

Completion Date: August 24, 2014

Recomplete Date: November 08, 2018

Purchaser/Measurer:

First Sales Date:

Completion Type	Location Exception	Increased Density
Single Zone	Order No	Order No
Multiple Zone	There are no Location Exception records to display.	There are no Increased Density records to display.
Commingled		

				Ca	ising and Cer	nent					
Туре		Size	Weight	Grade	ide Feet		PSI SAX		Top of CMT		
SU	RFACE		10.75	45.5	J55	989					
INTER	MEDIATE		7.625	29.7	L80	68	90		410	2637	
Liner											
Туре	Size	Weig	ght	Grade	Length	PSI	SAX	Top Depth		Bottom Depth	
	1	1	<u>I</u>	There are r	no Liner record	ds to displa	ay.	1		1	

Total Depth: 10031

Pac	ker	Plug			
Depth	Brand & Type	Depth	Plug Type		
7023.02	AS1X	7460	10K CIBP		

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
	There are no Initial Data records to display.									
	Completion and Test Data by Producing Formation									
Formation Name: WILCOX				Code:						
Spacing Orders					Perforated I					
Orde	er No U	nit Size		Fro	m	То				
There a	There are no Spacing Order records to display.			7080		7178				
	Acid Volumes				Fracture Tre					
15% ACID, 119BBL			2	0/40 WHITE	SAND 225,400L 4797BBL PI					
Formation Top				Were open hole	ogs run? No					
WICOX			0	Date last log run:						
				Were unusual drilling circumstances encoun Explanation:			untered? No			

Other Remarks	
PERMIT #1900330038	

FOR COMMISSION USE ONLY

Status: Accepted

December 16, 2019

1141300