

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35015233130000

Completion Report

Spud Date: July 19, 2019

OTC Prod. Unit No.: 015-226276

Drilling Finished Date: August 13, 2019

1st Prod Date: October 21, 2019

Completion Date: October 15, 2019

Drill Type: HORIZONTAL HOLE

Well Name: DOROTHA 33-9N-11W 1H

Purchaser/Measurer: COFFEYVILLE RESOURCES
REF AND MKTG

Location: CADD0 28 9N 11W
SW SW SE SE
265 FSL 1100 FEL of 1/4 SEC
Latitude: 35.2191911337 Longitude: -98.3628298323
Derrick Elevation: 0 Ground Elevation: 1408

First Sales Date: 10/22/2019

Operator: KAISER-FRANCIS OIL COMPANY 6390

6733 S YALE AVE
TULSA, OK 74121-1468

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	708940		690214	
	Commingled				

Casing and Cement								
Type		Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE		9.625	36	J55	1021		323	SURFACE
PRODUCTION		7	23	P110	9671		1055	750

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
LINER	4.5	13.5	P110	6409	0	610	9428	15837

Total Depth: 15860

Packer		Plug	
Depth	Brand & Type	Depth	Plug Type
There are no Packer records to display.		15811	CEMENT

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Oct 21, 2019	MARCHAND	358	42	265	740	690	FLOWING	300	48	200

Completion and Test Data by Producing Formation

Formation Name: MARCHAND

Code: 405 MRCD

Class: OIL

Spacing Orders

Order No	Unit Size
204540	640

Perforated Intervals

From	To
10777	15767

Acid Volumes

51651 G. ACID

Fracture Treatments

126188 BBLS SW PLUS 5.86MM LBS SAND

Formation	Top
HOXBAR	8111
UPPER WADE	8487
LOWER WADE	8967
MEDRANO	9351
HOGSHOOTER	10086
MARCHAND	10406

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

There are no Other Remarks.

Lateral Holes

Sec: 33 TWP: 9N RGE: 11W County: CADDO

SW SW SE SE

74 FSL 1264 FEL of 1/4 SEC

Depth of Deviation: 9757 Radius of Turn: 573 Direction: 175 Total Length: 900

Measured Total Depth: 15860 True Vertical Depth: 10392 End Pt. Location From Release, Unit or Property Line: 74

FOR COMMISSION USE ONLY

1144339

Status: Accepted