Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

OTC Prod. Unit No.: 073-224593-0-0000 Drilling Finished Date: August 14, 2018

1st Prod Date: November 21, 2018

Completion Date: October 28, 2018

Drill Type: HORIZONTAL HOLE

Min Gas Allowable: Yes

Well Name: LUCKY DOG 1507 7H-19 Purchaser/Measurer: MARKWEST

Location: KINGFISHER 19 15N 7W First Sales Date: 11/21/2018

W2 NE NW NW 330 FNL 960 FWL of 1/4 SEC

Latitude: 35.768153 Longitude: -97.991257 Derrick Elevation: 1209 Ground Elevation: 1181

Operator: NEWFIELD EXPLORATION MID-CON INC 20944

4 WATERWAY AVE STE 100 THE WOODLANDS, TX 77380-2764

Completion Type				
Х	Single Zone			
	Multiple Zone			
	Commingled			

Location Exception
Order No
694952

Increased Density	
Order No	
679402	

Casing and Cement							
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9 5/8"	36#	J-55	1483		390	SURFACE
PRODUCTION	5 1/2"	20#	P-110	13779		1530	SURFACE

				Liner				
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 13807

Packer				
Depth	Brand & Type			
There are no Packer records to display.				

Plug				
Depth Plug Type				
There are no Plug records to display.				

Initial Test Data

May 20, 2019 1 of 2

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Jan 03, 2019	MISSISSIPPIAN (LESS CHESTER)	387	40	522	1349	575	FLOWING	1000	34	240

Completion and Test Data by Producing Formation

Formation Name: MISSISSIPPIAN (LESS

CHESTER)

Code: 359MSNLC

Class: OIL

Spacing Orders					
Order No	Unit Size				
678038	640				

Perforated Intervals				
From	То			
9156	13710			

Acid Volumes 224 BBLS

Fracture Treatments	
TOTAL FLUIDS: 241,385 BBLS. TOTAL PROPPANT: 10,844,592 LBS	

Formation	Тор
MISSISSIPPIAN (LESS CHESTER)	8551

Were open hole logs run? No Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

There are no Other Remarks.

Lateral Holes

Sec: 19 TWP: 15N RGE: 7W County: KINGFISHER

SE SE SW SW

91 FSL 1019 FWL of 1/4 SEC

Depth of Deviation: 8320 Radius of Turn: 382 Direction: 180 Total Length: 4556

Measured Total Depth: 13807 True Vertical Depth: 9002 End Pt. Location From Release, Unit or Property Line: 91

FOR COMMISSION USE ONLY

1141465

Status: Accepted

May 20, 2019 2 of 2