Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000 Rule 165: 10-3-25

OTC Prod. Unit No.: 045-226691 Drilling Finished Date: September 18, 2019

1st Prod Date: January 14, 2020

Completion Date: January 10, 2020

Drill Type: HORIZONTAL HOLE

Well Name: BAYLESS 36X1-20-24 1HB Purchaser/Measurer: ENABLE

Location: ELLIS 25 20N 24W

NW SW SW SE

417 FSL 2389 FEL of 1/4 SEC

Latitude: 36.1746667 Longitude: -99.7109083 Derrick Elevation: 2435 Ground Elevation: 2417

Operator: FOURPOINT ENERGY LLC 23429

100 SAINT PAUL ST STE 400 DENVER, CO 80206-5140

	Completion Type
Х	Single Zone
	Multiple Zone
	Commingled

Location Exception				
Order No				
710564				

Increased Density				
Order No				
685322				
710317				
705117				

First Sales Date: 1/14/20

Casing and Cement								
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT	
SURFACE	9 5/8	36	J-55	825	432	365	SURFACE	
INTERMEDIATE	7	29	P-110CY	7904	1300	460	7881	
PRODUCTION	4 1/2	13/5	P-110	19283	700	755	6219	

Liner									
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth	
There are no Liner records to display.									

Total Depth: 19293

Packer					
Depth	Brand & Type				
8369	AS1-X				

Plug					
Depth	Plug Type				
There are no Plug records to display.					

Initial Test Data

April 21, 2020 1 of 2

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Feb 14, 2020	CLEVELAND	195	45	578	2964	607	PUMPING	570	64/64	105

Completion and Test Data by Producing Formation

Formation Name: CLEVELAND

Code: 405CLVD

Class: GAS

Spacing Orders					
Order No	Unit Size				
153956	640				
602840	640				
710563	MULTI UNIT				

Perforated Intervals				
From	То			
8925	19146			

Acid Volumes

50,417 GALS FE 15%

Fracture Treatments

10,387,850 LBS 40/70 REIONAL SAND, 800,500 LBS 40/70 KRT SAND, 1,001,790 LBS 40/70 KRT VOYAGER SAND. 264,730 BBLS WATER.

Formation	Тор
CLEVELAND	8661

Were open hole logs run? No Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

There are no Other Remarks.

Lateral Holes

Sec: 1 TWP: 19N RGE: 24W County: ELLIS

SE SE SE SW

34 FSL 2454 FWL of 1/4 SEC

Depth of Deviation: 8041 Radius of Turn: 592 Direction: 181 Total Length: 10323

Measured Total Depth: 19293 True Vertical Depth: 8665 End Pt. Location From Release, Unit or Property Line: 34

FOR COMMISSION USE ONLY

1144946

Status: Accepted

April 21, 2020 2 of 2