

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35073262260001

Completion Report

Spud Date: July 07, 2019

OTC Prod. Unit No.: 073-225975-0-0000

Drilling Finished Date: July 20, 2019

1st Prod Date: August 27, 2019

Completion Date: August 14, 2019

Drill Type: HORIZONTAL HOLE

Well Name: SAND HILLS 25-15N-6W 1MH

Purchaser/Measurer: ANCOVA

Location: KINGFISHER 25 15N 6W
NW NE NE NE
235 FNL 605 FEL of 1/4 SEC
Latitude: 35.754050303 Longitude: -97.782301005
Derrick Elevation: 1195 Ground Elevation: 1174

First Sales Date: 8/27/19

Operator: PALOMA OPERATING CO INC 23932

1100 LOUISIANA ST STE 5100
HOUSTON, TX 77002-5220

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	705690		There are no Increased Density records to display.	
	Commingled	709049			

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9.625	36	J-55	1373		485	SURFACE
PRODUCTION	7	29	P-110	7487		250	3905

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
LINER	4.5	13.5	P-110	7306	0	240	5146	12452

Total Depth: 12462

Packer	
Depth	Brand & Type
7589	VS-1X

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Sep 08, 2019	MISSISSIPPIAN	464	37			1191	FLOWING	860	64/64	1245

Completion and Test Data by Producing Formation			
Formation Name: MISSISSIPPIAN		Code: 359MSSP	Class: OIL
Spacing Orders		Perforated Intervals	
Order No	Unit Size	From	To
681164	640	7618	12313
Acid Volumes		Fracture Treatments	
NONE		258,421 BBLS FLUID 12,749,732 LBS PROPPANT	

Formation	Top
MISSISSIPPIAN	7406

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks
There are no Other Remarks.

Lateral Holes
Sec: 25 TWP: 15N RGE: 6W County: KINGFISHER
SE SE SW SE
66 FSL 1189 FEL of 1/4 SEC
Depth of Deviation: 6982 Radius of Turn: 500 Direction: 182 Total Length: 4695
Measured Total Depth: 12462 True Vertical Depth: 7425 End Pt. Location From Release, Unit or Property Line: 66

FOR COMMISSION USE ONLY	
Status: Accepted	1143613