Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000 Rule 165: 10-3-25

API No.: 35051247350002

OTC Prod. Unit No.: 051-226926

Completion Report

Spud Date: November 29, 2019

Drilling Finished Date: December 19, 2019 1st Prod Date: August 25, 2020 Completion Date: August 18, 2020

Drill Type: HORIZONTAL HOLE

Well Name: MILLS 4-16-21XHW

- Location: GRADY 16 7N 5W SE NE SW NE 1715 FNL 1581 FEL of 1/4 SEC Latitude: 35.08295 Longitude: -97.729071 Derrick Elevation: 1273 Ground Elevation: 1246
- Operator: CONTINENTAL RESOURCES INC 3186 PO BOX 268870 20 N BROADWAY AVE OKLAHOMA CITY, OK 73126-8870

Purchaser/Measurer: ENABLE MIDSTREAM

First Sales Date: 08/25/2020

Completion Type	Completion Type Location Exception						Increased Density						
X Single Zone		Order No					Order No						
Multiple Zone		714910					704972						
Commingled	705338												
	Casing and Cement												
	Type SURFACE PRODUCTION			Size	Weight	Grade			PSI	SAX	Top of CMT		
				20	133	J-55				820	SURFACE		
				5.50 23		P-110	P-110 20148		2915		980		
					•	Liner	•	•		•	•		
	Туре	Size	Weigh	t	Grade	Length	PSI	SAX	То	p Depth	Bottom Depth		
	There are no Liner records to display.												

Total Depth: 20175

Pac	ker	Plug			
Depth	Brand & Type	Depth	Plug Type		
There are no Packe	r records to display.	There are no Plug records to display.			

				Initial Tes	t Data					
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Aug 28, 2020	WOODFORD	160	46.42	631	3943	3386	FLOWING	1835	34/64	757

				Class: OIL			
Formation I	Code: 3	319 WDFD					
Spacin		Perforated]				
Order No	Unit Size	From		То			
644200	640	11610		15111			
593309 640		15130		20006			
714909	MULTIUNIT		L		_		
Acid Volumes There are no Acid Volume records to display.		Fracture Treatments					
		354,976 B	BLS FLUID & 19]			
ormation	Тор		Were open hole	logs run? No			
NOODFORD		11610					
			Were unusual d	rilling circumstances encoun	tered? No		
			Explanation:				

There are no Other Remarks.

Lateral Holes

Sec: 21 TWP: 7N RGE: 5W County: GRADY

SW SE SW SE

258 FSL 1847 FEL of 1/4 SEC

Depth of Deviation: 11152 Radius of Turn: 576 Direction: 172 Total Length: 8565

Measured Total Depth: 20175 True Vertical Depth: 11720 End Pt. Location From Release, Unit or Property Line: 329

FOR COMMISSION USE ONLY

Status: Accepted

1145551