

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35015233250000

Completion Report

Spud Date: March 16, 2022

OTC Prod. Unit No.: 01522820100000

Drilling Finished Date: June 08, 2022

1st Prod Date: August 20, 2022

Completion Date: August 15, 2022

Drill Type: HORIZONTAL HOLE

Well Name: SERGEANT MAJOR 18-19-30-9-10 #1HXL

Purchaser/Measurer: MUSTANG

Location: CADD0 18 9N 10W
NE NW NE SW
2416 FSL 1801 FWL of 1/4 SEC
Latitude: 35.25392528 Longitude: -98.30007373
Derrick Elevation: 1274 Ground Elevation: 1251

First Sales Date: 08-26-2022

Operator: LYNX OKLAHOMA OPERATING LLC 24306

PO BOX 18548
OKLAHOMA CITY, OK 73154-0548

Completion Type	
X	Single Zone
	Multiple Zone
	Commingled

Location Exception
Order No
729120

Increased Density
Order No
There are no Increased Density records to display.

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
CONDUCTOR	20	52	X-42	115			SURFACE
SURFACE	9-5/8	36	J-55	1972		501	SURFACE
PRODUCTION	5-1/2	20	P-110RY	19812		2552	5750

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 19822

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Sep 01, 2022	MARCHAND	112	47	127	1100	702	FLOWING	1200	64/64	295

Completion and Test Data by Producing Formation

Formation Name: MARCHAND

Code: 405MRCD

Class: OIL

Spacing Orders

Order No	Unit Size
729119	MULTIUNIT
720705	640
720706	640
702809	640

Perforated Intervals

From	To
10310	12431
12431	17722
17722	19714

Acid Volumes

1038 BBLS HCL

Fracture Treatments

370,984 BBLS FLUID 15,290,126 LBS PROPPANT

Formation	Top
MARCHAND	8680

Were open hole logs run? No
Date last log run:

Were unusual drilling circumstances encountered? No
Explanation:

Other Remarks

There are no Other Remarks.

Lateral Holes

Sec: 30 TWP: 9N RGE: 10W County: CADD0

NE SE SE NW

2090 FNL 2527 FWL of 1/4 SEC

Depth of Deviation: 9261 Radius of Turn: 739 Direction: 180 Total Length: 9512

Measured Total Depth: 19822 True Vertical Depth: 10042 End Pt. Location From Release, Unit or Property Line: 2090

FOR COMMISSION USE ONLY

Status: Accepted

1148873