

Oklahoma Corporation Commission  
Oil & Gas Conservation Division  
Post Office Box 52000  
Oklahoma City, Oklahoma 73152-2000  
Rule 165: 10-3-25

Form 1002A

API No.: 35049252390002

**Completion Report**

Spud Date: February 12, 2019

OTC Prod. Unit No.: 049-225548-0-0000

Drilling Finished Date: March 17, 2019

1st Prod Date: July 29, 2019

Completion Date: May 07, 2019

**Drill Type: HORIZONTAL HOLE**

Well Name: BUD 6-12-1 WXH

Purchaser/Measurer: SOUTHWEST

Location: GARVIN 13 3N 4W  
SW SE NE NW  
1168 FNL 2109 FWL of 1/4 SEC  
Latitude: 34.735940447 Longitude: -97.573208784  
Derrick Elevation: 1157 Ground Elevation: 1137

First Sales Date: 08/02/2019

Operator: CASILLAS OPERATING LLC 23838

401 S BOSTON AVE STE 2400  
TULSA, OK 74103-4060

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	703970		688079	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9.625	40.00	J-55	1477		375	SURFACE
PRODUCTION	5.5	20.00	P-110CYHP	22936		2125	2571

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

**Total Depth: 22958**

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Sep 22, 2019	WOODFORD	323	45	2225	6889	1291	FLOWING	965	128/128	225

**Completion and Test Data by Producing Formation**

Formation Name: WOODFORD

Code: 319WDFD

Class: OIL

**Spacing Orders**

Order No	Unit Size
677714	640
703969	MULTIUNIT

**Perforated Intervals**

From	To
12577	22833

**Acid Volumes**

762 BBLS HCL ACID
-------------------

**Fracture Treatments**

591,265 BBLS FLUID 19,308,950 LBS PROPPANT
---

Formation	Top
WOODFORD	12209

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

**Other Remarks**

There are no Other Remarks.

**Lateral Holes**

Sec: 1 TWP: 3N RGE: 4W County: GARVIN

NE NE NE NW

50 FNL 2311 FWL of 1/4 SEC

Depth of Deviation: 11926 Radius of Turn: 475 Direction: 2 Total Length: 10256

Measured Total Depth: 22958 True Vertical Depth: 11416 End Pt. Location From Release, Unit or Property Line: 50

**FOR COMMISSION USE ONLY**

1143848

Status: Accepted