

Oklahoma Corporation Commission
 Oil & Gas Conservation Division
 Post Office Box 52000
 Oklahoma City, Oklahoma 73152-2000
 Rule 165: 10-3-25

Form 1002A

API No.: 35051246810000

Completion Report

Spud Date: July 28, 2019

OTC Prod. Unit No.: 051-226871-0-0000

Drilling Finished Date: August 22, 2019

1st Prod Date: July 29, 2020

Completion Date: July 17, 2020

Drill Type: HORIZONTAL HOLE

Min Gas Allowable: Yes

Well Name: JACQUEZ 5-18-19XHW

Purchaser/Measurer: ENABLE MIDSTREAM

Location: GRADY 18 7N 5W
 E2 SE SW NE
 2310 FNL 1405 FEL of 1/4 SEC
 Latitude: 35.081345 Longitude: -97.763461
 Derrick Elevation: 1251 Ground Elevation: 1224

First Sales Date: 7/29/2020

Operator: CONTINENTAL RESOURCES INC 3186
 PO BOX 268870
 20 N BROADWAY AVE
 OKLAHOMA CITY, OK 73126-8870

Completion Type	
X	Single Zone
	Multiple Zone
	Commingled

Location Exception	
Order No	
713356	

Increased Density	
Order No	
700297	
700298	

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9.625	40	J-55	1496		460	SURFACE
PRODUCTION	5.50	23	P-110 ICY	20120		2570	504

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 20130

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Jul 31, 2020	WOODFORD	212	43.27	314	1481	3831	FLOWING	2000	40/64	531

Completion and Test Data by Producing Formation

Formation Name: WOODFORD

Code: 319WDFD

Class: OIL

Spacing Orders

Order No	Unit Size
621966	640
713099	MULTIUNIT

Perforated Intervals

From	To
12150	14874
14903	19932

Acid Volumes

1556 BBLS 15% HCl

Fracture Treatments

354,192 BBLS FLUID & 18,474,105 LBS OF SAND

Formation	Top
WOODFORD	12150

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

There are no Other Remarks.

Lateral Holes

Sec: 19 TWP: 7N RGE: 5W County: GRADY

SW SE SE SE

52 FSL 1558 FEL of 1/4 SEC

Depth of Deviation: 11515 Radius of Turn: 721 Direction: 180 Total Length: 7980

Measured Total Depth: 20130 True Vertical Depth: 12218 End Pt. Location From Release, Unit or Property Line: 52

FOR COMMISSION USE ONLY

1145182

Status: Accepted