

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35087222490000

Completion Report

Spud Date: July 01, 0319

OTC Prod. Unit No.: 087-226160-0-0000

Drilling Finished Date: July 22, 2019

1st Prod Date: November 17, 2019

Completion Date: September 21, 2019

Drill Type: HORIZONTAL HOLE

Well Name: JAMESON 3-6WH

Purchaser/Measurer: SOUTHWEST

Location: MCCLAIN 6 5N 4W
SE NW NW NE
500 FNL 2023 FEL of 1/4 SEC
Latitude: 34.94101467 Longitude: -97.6595732
Derrick Elevation: 1195 Ground Elevation: 1180

First Sales Date: 11/17/2019

Operator: CASILLAS OPERATING LLC 23838

401 S BOSTON AVE STE 2400
TULSA, OK 74103-4060

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	There are no Location Exception records to display.		710229	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9.625	40.00	J-55	1506		375	SURFACE
PRODUCTION	5.5	20.00	P-110	17142		1205	5215

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 17180

Packer		Plug	
Depth	Brand & Type	Depth	Plug Type
There are no Packer records to display.		There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Jan 11, 2020	WOODFORD	641	49	1726	2693	839	FLOWING	1731	128/128	1171

Completion and Test Data by Producing Formation

Formation Name: WOODFORD

Code: 319WDFD

Class: OIL

Spacing Orders

Order No	Unit Size
698903	640

Perforated Intervals

From	To
12101	17028

Acid Volumes

258 BBLS HCL ACID

Fracture Treatments

305,068 BBLS FLUID 9,969,640 LBS PROPPANT
--

Formation	Top
WOODFORD	12096

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

There are no Other Remarks.

Lateral Holes

Sec: 6 TWP: 5N RGE: 4W County: MCCLAIN

SE SW SE SW

26 FSL 1856 FWL of 1/4 SEC

Depth of Deviation: 11698 Radius of Turn: 354 Direction: 182 Total Length: 4927

Measured Total Depth: 17180 True Vertical Depth: 11435 End Pt. Location From Release, Unit or Property Line: 26

FOR COMMISSION USE ONLY

1144686

Status: Accepted