

Oklahoma Corporation Commission  
Oil & Gas Conservation Division  
Post Office Box 52000  
Oklahoma City, Oklahoma 73152-2000  
Rule 165: 10-3-25

Form 1002A

API No.: 35087222510000

**Completion Report**

Spud Date: July 23, 2019

OTC Prod. Unit No.: 087-226162-0-0000

Drilling Finished Date: August 17, 2019

1st Prod Date: November 15, 2019

Completion Date: September 19, 2019

**Drill Type: HORIZONTAL HOLE**

Well Name: JAMESON 5-6WH

Purchaser/Measurer: SOUTHWEST

Location: MCCLAIN 6 5N 4W  
SE NW NW NE  
530 FNL 2023 FEL of 1/4 SEC  
Latitude: 34.94093221 Longitude: -97.65957237  
Derrick Elevation: 1200 Ground Elevation: 1185

First Sales Date: 11/22/2019

Operator: CASILLAS OPERATING LLC 23838

401 S BOSTON AVE STE 2400  
TULSA, OK 74103-4060

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	There are no Location Exception records to display.		710229	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9.625	40.00	J-55	1490		375	SURFACE
PRODUCTION	5.5	20.00	P-110	16928		1205	5123

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

**Total Depth: 16939**

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Dec 26, 2019	WOODFORD	356	47	1160	3258	582	FLOWING	1640	128/128	1121

**Completion and Test Data by Producing Formation**

Formation Name: WOODFORD

Code: 319WDFD

Class: OIL

**Spacing Orders**

Order No	Unit Size
698903	640

**Perforated Intervals**

From	To
11819	16790

**Acid Volumes**

145 BBLS HCL ACID
-------------------

**Fracture Treatments**

302,460 BBLS FLUID 9,930,992 LBS PROPPANT
--

Formation	Top
WOODFORD	11810

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

**Other Remarks**

There are no Other Remarks.

**Lateral Holes**

Sec: 6 TWP: 5N RGE: 4W County: MCCLAIN

SW SE SW SE

27 FSL 1887 FEL of 1/4 SEC

Depth of Deviation: 11416 Radius of Turn: 370 Direction: 179 Total Length: 4971

Measured Total Depth: 16939 True Vertical Depth: 11408 End Pt. Location From Release, Unit or Property Line: 27

**FOR COMMISSION USE ONLY**

1144689

Status: Accepted