

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35125239550001

Completion Report

Spud Date: January 27, 2021

OTC Prod. Unit No.: 125-227079-0-0000

Drilling Finished Date: February 03, 2021

1st Prod Date: April 02, 2021

Completion Date: March 05, 2021

Drill Type: STRAIGHT HOLE

Well Name: HAYNES 1-4

Purchaser/Measurer:

Location: POTTAWATOMIE 4 7N 5E
NE SE SW SE
653 FSL 1420 FEL of 1/4 SEC
Latitude: 35.10290951 Longitude: -96.78001498
Derrick Elevation: 893 Ground Elevation: 878

First Sales Date:

Operator: REACH OIL AND GAS COMPANY INC 24558

6301 WATERFORD BLVD STE 120
OKLAHOMA CITY, OK 73118-1100

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	There are no Location Exception records to display.		There are no Increased Density records to display.	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	8 5/8	24	8RD	800		430	SURFACE
PRODUCTION	5 1/2	15.50	8RD	4430		145	3630

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 4446

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Apr 02, 2021	SIMPSON DOLOMITE	20	38			46	PUMPING			

Completion and Test Data by Producing Formation			
Formation Name: SIMPSON DOLOMITE		Code: 202SMPSD	Class: OIL
Spacing Orders		Perforated Intervals	
Order No	Unit Size	From	To
715798	80	4270	4280
Acid Volumes		Fracture Treatments	
1000 GAL 15% HCL		There are no Fracture Treatments records to display.	

Formation	Top
CALVIN	2933
EARLSBORO	3328
WOODFORD	4039
SYLVAN	4121
VIOLA	4180
SIMPSON DOLOMITE	4267
1ST WILCOX	4314
2ND WILCOX	4386

Were open hole logs run? Yes
Date last log run:

Were unusual drilling circumstances encountered? No
Explanation:

Other Remarks
There are no Other Remarks.

FOR COMMISSION USE ONLY	
Status: Accepted	1146252