Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35125239490000 Completion Report Spud Date: September 25, 2019

OTC Prod. Unit No.: 125-226270-0-0000 Drilling Finished Date: October 02, 2019

1st Prod Date: November 22, 2019

Completion Date: November 01, 2019

Drill Type: STRAIGHT HOLE

Well Name: JOE SMITH TRUST 2 Purchaser/Measurer:

Location: POTTAWATOMIE 28 8N 4E

NW NW NW SW

165 FNL 165 FWL of 1/4 SEC

Derrick Elevation: 950 Ground Elevation: 938

Operator: GILLHAM PAUL OIL COMPANY 18920

PO BOX 699

105 E WANDA JACKSON BLVD MAUD, OK 74854-0699

	Completion Type
Х	Single Zone
	Multiple Zone
	Commingled

Location Exception
Order No
702867

Increased Density						
Order No						
There are no Increased Density records to display.						

First Sales Date:

Casing and Cement									
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT		
SURFACE	8 5/8	24	NEW	302	500	220	SURFACE		
PRODUCTION	5.5	15.5	NEW	4410	800	170	3246		

				Liner				
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
	-		There are	no Liner record	ds to displa	ay.		

Total Depth: 4570

Packer					
Depth Brand & Type					
There are no Packer records to display.					

Plug					
Depth	Plug Type				
4330	CIBP				
4360	CIBP				

Initial Test Data

January 15, 2020 1 of 2

Test Date	Formati	on	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Nov 22, 2019	HUNTO	NC	8.35	38	25	2994	85	PUMPING	650		
			Con	npletion an	d Test Data k	y Producing F	ormation				
	Formation Na	ame: VIOLA			Code: 20	2VIOL	С	class: DRY			
	Spacing	Orders				Perforated I	ntervals				
Order No Unit Size		$\neg \vdash$	Fron	n	То						
684	306		160		4366	5	43	370			
	Acid Vo	lumes				Fracture Tre	atments				
600 GALLONS 15%, 35 BARRELS WATER				There are no	Fracture Treatn	nents record	s to display.				
	Formation Na	ame: HUNT	ON		Code: 26	9HNTN	C	class: OIL			
	Spacing	Orders				Perforated I	ntervals				
Orde	r No	Uı	nit Size	$\exists \vdash$	From		7	Го	7		
684	306		160		4040)	4104				
	Acid Vo	lumes				Fracture Tre	atments				

Formation	Тор
UPPER CALVIN	3159
LOWER CALVIN	3379
EARLSBORO	3728
BARTLESVILLE	3835
WOODFORD	3859
HUNTON	3900
SYLVAN	4130
VIOLA	4220
WILCOX	4431

20,000 GALLONS 15%, 400 BARRELS WATER

Were open hole logs run? Yes
Date last log run: October 01, 2019

There are no Fracture Treatments records to display.

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

There are no Other Remarks.

FOR COMMISSION USE ONLY

1144320

Status: Accepted

January 15, 2020 2 of 2

A record of the formations drilled through, and pertinent remarks are presented on the reverse. I declare that I have knowledge of the contents of this report and am authorized by my organization to make this report, which was prepared by me or under my supervision and direction, with the data and facts stated herein to be true, correct, and complete to the best of my knowledge and belief.

650 PSI

SIGNATURE

INITIAL SHUT-IN PRESSURE

FLOW TUBING PRESSURE

CHOKE SIZE

STEVEN GILLHAM

NAME (PRINT OR TYPE)

Dec 1,2019

(405) 406-8787 PHONE NUMBER Form 1002A


Rev. 2009

LEASE NAME	JOE SMITH TRUST	WELL NO.	2

	FO	R COMMISSION USE ONLY
ITD on file	YES NO	
APPROVED	DISAPPROVED	2) Reject Codes

Were open hole logs run?	X_ yes	no				
Date Last log was run		10/1/2	:019			
Was CO ₂ encountered?	yes	X no	at what depths?	3		
Was H ₂ S encountered?	yes	X no	at what depths?			
Were unusual drilling circumstand If yes, briefly explain below	es encountere	d?	<u> </u>	yes	X no	

Other remarks:		
	F	



If more than three drainholes are proposed, attach a separate sheet indicating the necessary information.

Direction must be stated in degrees azimuth. Please note, the horizontal drainhole and its end point must be located within the boundaries of the lease or spacing unit.

Directional surveys are required for all drainholes and directional wells.

		640	Acres			
					4	
	2	,				
					- Ass	
				1.7.3		

BOTTOM HOLE LOCATION FOR DIRECTIONAL HOLE

SEC TWP	RGE	COUNT	Υ			
Spot Location 1/4	1/4	1/4	1/4 Fee	t From 1/4 Sec Lines	FSL	FWL
Measured Total Depth True Vertical Depth		BHL	BHL From Lease, Unit, or Property Line:			

BOTTOM HOLE LOCATION FOR HORIZONTAL HOLE: (LATERALS)

LATERAL #1

SEC TWP	RGE		COUNTY			
Spot Location 1/4	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Depth of Deviation		Radius of Turn		Direction	Total Length	Tarasa a
Measured Total Depth		True Vertical Dep	th	BHL From Lease, Unit, or P		

LATERAL #2

SEC	TWP	RGE	COUN	ITY			
Spot Loc	cation 1/4	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Depth of Deviation		Ra	dius of Turn		Direction	Total Length	- Providence of
Measure	ed Total Depth	Tru	ue Vertical Depth		BHL From Lease, Unit, or Pr		

LATERAL #3

SEC	TWP	RGE	C	OUNTY			
Spot Locati	on 1/4	1/4	1/4	1/	Feet From 1/4 Sec Lines	FSL	FWL
Depth of Deviation			Radius of Turn		Direction	Total Length	
Measured 1	Fotal Depth		True Vertical Depti	1	BHL From Lease, Unit, or Pr		