Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000 Rule 165: 10-3-25

API No.: 35121248990000

Well Name: EAGLE 1-32-29WH

Drill Type:

Location:

OTC Prod. Unit No.: 121-228269-0-0000

Completion Report

Spud Date: May 30, 2022

Drilling Finished Date: July 09, 2022

1st Prod Date: October 06, 2022

Completion Date: September 29, 2022

Purchaser/Measurer: BP ENERGY

First Sales Date: 10/06/2022

Operator: CALYX ENERGY III LLC 23515

SE SE NE NW

HORIZONTAL HOLE

PITTSBURG 5 7N 13E

1090 FNL 2476 FWL of 1/4 SEC

Latitude: 35.11332981 Longitude: -95.95731425 Derrick Elevation: 986 Ground Elevation: 960

6120 S YALE AVE STE 1480 TULSA, OK 74136-4226

Completion Type		Location Exception	Increased Density
Х	Single Zone	Order No	Order No
	Multiple Zone	729686	729524
	Commingled		

Casing and Cement											
Туре			Size	Weight	Grade	Feet		PSI	SAX	Top of CMT	
CONE	DUCTOR		16			40			3	SURFACE	
SURFACE			9.625	36#	J55	505			155	SURFACE	
PRODUCTION			5.5	20#	P-110	15203		1630		2270	
Liner											
Туре	Type Size Weight		ght	Grade	Length	PSI SAX		Тор	Depth	Bottom Depth	

Total Depth: 15639

Pac	ker	Plug				
Depth	Brand & Type	Depth	Plug Type			
There are no Packe	r records to display.	3024	BALANCED CEMENT			

Initial Test Data

Test Date	Forma	tion	Oil BBL/Day	Oil-Gra (AP		Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure		
Nov 05, 2022	WOODI	FORD	7		2	13504	1929143	3369	FLOWING	338	Open	282		
Completion and Test Data by Producing Formation														
Formation Name: WOODFORD Code: 319WDFD Class: GAS														
	Spacing	g Orders					Perforated							
Orde	Order No Unit Size					From To								
720	707		1280			6367 15050								
	Acid V	olumes					Fracture Tre							
	1,390 BARRE	ELS 7.5% HC			\vdash	287	,787 BARREL	_						
						7,9	02,453 POUNE	-						
Formation			Т	ор		Were open hole logs run? No								
WOODFORD 5878 Date last log run:														
	Were unusual drilling circumstances encountered? Yes													
Explanation: TOOLS WERE LOST IN HOLE WHILE TRIPPING IN THE HOLE TO CONTINUE DRILLING THE LATERAL. CALYX SET A CEMENT BRIDGE PLUG FROM 3,023' TO 2,297' AND THEN RE-DRILLED A SECOND LATERAL PARALLEL TO THE FIRST.														
Other Remark	S													
There are no C	ther Remarks.													
						Lateral F	loles							
Sec: 29 TWP:	8N RGE: 13E (County: PITT	SBURG											
SE NW NE NE														
628 FNL 668 FEL of 1/4 SEC														
Depth of Deviation: 5551 Radius of Turn: 415 Direction: 360 Total Length: 8683														
Measured Total Depth: 15639 True Vertical Depth: 5190 End Pt. Location From Release, Unit or Property Line: 628														
FOR COM	IISSION US	E ONLY												
												1149156		

Status: Accepted