## Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35043236260000 **Completion Report** Spud Date: May 14, 2018

OTC Prod. Unit No.: 043-223726 Drilling Finished Date: June 10, 2018

1st Prod Date: August 06, 2018

Completion Date: August 06, 2018

**Drill Type: HORIZONTAL HOLE** 

Well Name: LEAH 32-18N-19W 1CH Purchaser/Measurer:

DEWEY 32 18N 19W NE NE NE NW Location:

200 FNL 2450 FWL of 1/4 SEC

Latitude: 35.999432 Longitude: -99.248839 Derrick Elevation: 1926 Ground Elevation: 1901

WHITE STAR PETROLEUM II LLC 23275 Operator:

PO BOX 13360

301 NW 63RD ST STE 600 **OKLAHOMA CITY, OK 73113-1360** 

	Completion Type
Х	Single Zone
	Multiple Zone
	Commingled

Location Exception
Order No
696575

Increased Density				
Order No				
There are no Increased Density records to display.				

First Sales Date:

Casing and Cement								
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT	
SURFACE	9-5/8"	36#	J-55	1500		595	SURFACE	
INTERMEDIATE	7"	26#	P-110	8286		205	594	
PRODUCTION	4-1/2"	13.5#	P-110	13764		530	8111	

				Liner				
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 13765

Packer			
Depth	Brand & Type		
8489	AS1-X PACKER		

Plug				
Depth	Plug Type			
8737	CEMENT			
8736	2ND CEMENT			

**Initial Test Data** 

January 30, 2020 1 of 2

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Aug 18, 2018	CLEVELAND	68	44	40	588	1250	PUMPING			

### **Completion and Test Data by Producing Formation**

Formation Name: CLEVELAND

Code: 405CLVD

Class: OIL

Spacing Orders					
Order No	Unit Size				
512647	640				

Perforated Intervals				
From	То			
9085	13589			

Acid Volumes
600 BLS 15%HCL ACID

Fracture Treatments
113,000 BLS WATER
6,315,700 LBS SAND

Formation	Тор
CLEVELAND	8701

Were open hole logs run? No Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

#### Other Remarks

REPORTED TO FRACFOCUS 7/24/2018. DID NOT GET BUILD RATES, LANDED LOW IN SECTION. HAD TO SET PLUG, 1ST PLUG DID NOT SET. 2ND PLUG PLUG 8737-8154'. 3RD PLUG FROM 8736-8002'. BHL FROM PROPOSED PLAT.

#### **Lateral Holes**

Sec: 32 TWP: 18N RGE: 19W County: DEWEY

SE SE SW SE

174 FSL 1365 FEL of 1/4 SEC

Depth of Deviation: 8300 Radius of Turn: 722 Direction: 163 Total Length: 4331

Measured Total Depth: 13765 True Vertical Depth: 8899 End Pt. Location From Release, Unit or Property Line: 174

# FOR COMMISSION USE ONLY

1140336

Status: Accepted

January 30, 2020 2 of 2