Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000 Rule 165: 10-3-25

API No.: 35123031090004 **Completion Report** Spud Date: March 15, 1935

OTC Prod. Unit No.: Drilling Finished Date: April 21, 1935

1st Prod Date:

First Sales Date:

Amended

Amend Reason: CORRECTION SHOW ONLY VIOLA INJECTION

Completion Date: May 31, 1935

Recomplete Date: April 05, 2020

Drill Type: STRAIGHT HOLE

SERVICE WELL

Well Name: FITTS WEST UNIT 22-10 Purchaser/Measurer:

Location: PONTOTOC 30 2N 7E

C SW SW SE 330 FSL 330 FWL of 1/4 SEC

Latitude: 34.608289 Longitude: -96.607789 Derrick Elevation: 810 Ground Elevation: 0

FDL OPERATING LLC 24496 Operator:

Completion Type

Single Zone Multiple Zone Commingled

5221 N O'CONNOR BLVD STE 1100

IRVING, TX 75039-3788

Location Exception						
Order No						
There are no Location Exception records to display.						

Increased Density							
Order No							
There are no Increased Density records to display.							

Casing and Cement								
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT	
SURFACE	13 3/8	48		519		600	SURFACE	
INTERMEDIATE	8 5/8	32		3602		2200	1100	
PRODUCTION	5 1/2	14		4330		340	1680	

Liner								
Туре	Type Size Weight Grade Length PSI SAX Top Depth Bottom Depth							
There are no Liner records to display.								

Total Depth: 4330

Packer						
Depth	Brand & Type					
3641	AS-1X					

Plug						
Depth	Plug Type					
3900	PBTD					

Initial Test Data

July 21, 2020 1 of 2

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
There are no Initial Data records to display.										
		Con	npletion and	Test Data b	y Producing F	ormation				
Formation Name: VIOLA Code: 202VIOL Class: INJ										
Spacing Orders				Perforated Intervals						
Orde	er No Ui	nit Size		From To			╗			
70582 UNIT			3682	2	3844					
Acid Volumes			Fracture Treatments							
There are no Acid Volume records to display.			T	There are no Fracture Treatments records to display.						

Formation	Тор
GILCREASE	1240
CROMWELL	2252
WOODFORD	2716
CHIMNEY HILL	3168
VIOLA	3589

Were open hole logs run? No Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

UIC - ORDER 70582. THIS REPORT IS BEING SUBMITTED BASED ON LIMITED INFORMATION PROVIDED. THE GILCREASE WAS ABANDONED IN 1969 WHEN THEY RAN THE 5 1/2" CASING. CEMENTING NOTES SHOW THAT CEMENT CAME UPTO 1680' WHICH IS IN THE MIDDLE OF THE GILCREASE. IT ISN'T TECHNICALLY SQUEEZED BUT IT IS BEHIND PIPE. THE 5 1/2' CASING WAS NEVER PERFORATED IN THE GILCREASE. FDL IS INJECTING BELOW THE PACKER AT 3614'.

FOR COMMISSION USE ONLY

1145353

Status: Accepted

July 21, 2020 2 of 2

Form 1002A

Rev. 2009

PLEASE TYPE OR USE BLACK INK ONLY

FORMATION RECORD Give formation names and tops, if available, or descriptions and thickness of formations drilled through. Show intervals cored or drillstem tested. WELL NO. LEASE NAME NAMES OF FORMATIONS TOP FOR COMMISSION USE ONLY Gilcrease 1,240 ITD on file YES NO Cromwell 2,252 APPROVED DISAPPROVED 2) Reject Codes Woodford 2716 Chimney Hill 3,168 Viola 3,589 Were open hole logs run? yes _ Date Last log was run Was CO2 encountered? no at what depths? ves Was H2S encountered? ves Were unusual drilling circumstances encountered? If yes, briefly explain below The report is being submitted based on limited information provided. The Gilrease was abandoned in 1969 when they ran the 5-1/2" casing. Cementing notes show that cement came up to 1680' which is in the middle of the Gilcrease. It isn't technically squeezed, but it isn't active either. It is behind pipe. The 5-1/2" was never perforated in the Gilcrease. FDL is only injecting below the packer @ 3,641'. OCC - UIC order#70582 640 Acres **BOTTOM HOLE LOCATION FOR DIRECTIONAL HOLE** COUNTY Feet From 1/4 Sec Lines Spot Location FWL FSL Measured Total Deoth True Vertical Depth BHL From Lease, Unit, or Property Line: **BOTTOM HOLE LOCATION FOR HORIZONTAL HOLE: (LATERALS)** LATERAL #1 RGE COUNTY 1/4 Feet From 1/4 Sec Lines FWL FSL 1/4 Depth of Total Radius of Turn If more than three drainholes are proposed, attach a sured Total Depth True Vertical Depth BHL From Lease, Unit, or Property Line: varate sheet indicating the neces Direction must be stated in degrees azimuth.
Please note, the horizontal drainhole and its end point must be located within the houndaries of the LATERAL #2 lease or spacing unit. TWP RGE COUNTY Directional surveys are required for all 1/4 Feet From 1/4 Sec Lines FSL FWL drainholes and directional wells. Total 640 Acres Depth of Radius of Turn sured Total Depth True Vertical Depth BHL From Lease, Unit, or Property Lin LATERAL #3 TWP COUNTY RGE Spot Location FWL FSL Feet From 1/4 Sec Lines Total Depth of Deviation sured Total Depth True Vertical Depth BHL From Lease, Unit, or Property Line:

FDL Operating, LLC

July 7, 2020

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Attention: Jim Phelps
Administrative Programs Officer
P.O. Box 52000
Oklahoma City, Oklahoma 73152-2000

RE:

Fitts West Unit #22-10 Pontotoc County, OK API #35-123-03109

Dear Mr. Phelps,

Enclosed is a corrected Form 1002A for the above referenced well. The Gilcrease was abandoned in 1969 when they ran the 5-1/2" casing. Cement notes show that cement came up to 1680' which is in the middle of the Gilcrease. It isn't technically squeezed, but it isn't active either. It is behind pipe. The 5-1/2" was never perforated in the Gilcrease. FDL is only injecting below the packer at 3,641'.

Should you have any questions or need additional information, please contact me at <u>Julie.ward5825@sbcglobal.net</u> or cell 713-202-8950.

Sincerely,

Julia Ward

Regulatory Analyst

Julia Ward

/jaw

Enclosures