Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35011240410001 **Completion Report** Spud Date: May 17, 2019

OTC Prod. Unit No.: Drilling Finished Date: May 28, 2019

1st Prod Date:

First Sales Date:

Completion Date: June 15, 2019

Drill Type: STRAIGHT HOLE

SERVICE WELL

Well Name: SELBY SWD 1 Purchaser/Measurer:

BLAINE 23 15N 11W Location:

NE NE NE NW 278 FNL 165 FEL of 1/4 SEC

Derrick Elevation: 0 Ground Elevation: 0

VISTA DISPOSAL SOLUTIONS LLC 24198 Operator:

> 1803 ELTON LN AUSTIN, TX 78703-2915

Completion Type
Single Zone
Multiple Zone
Commingled

Location Exception
Order No
There are no Location Exception records to display.

Increased Density
Order No
There are no Increased Density records to display.

		Cas	sing and Ceme	ent			
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9 5/8			380		220	SURFACE
PRODUCTION	7			8130		680	3300

				Liner				
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
			There are	no Liner record	ds to displa	ay.		

Total Depth: 8130

Pac	ker
Depth	Brand & Type
3843	ARROW

Pl	ug
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data

November 20, 2019 1 of 3

Test Date	Format	ion	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubin Pressure
				There are	no Initial Data	records to disp	olay.	!	ļ		
			Con	pletion and	l Test Data k	y Producing F	ormation				
	Formation N	ame: WOLF	CAMPIAN		Code: 45	1WFMP	C	lass: COMM	DISP		
	Spacing	Orders				Perforated I	ntervals				
Order No Unit Size		\neg	Fron	1	7	ō	7				
There are no Spacing Order records to display.				3860)	38	378				
				_ _	3892	2	39	902			
					3922	2	39	936			
	Acid Vo	olumes		\neg \sqcap		Fracture Tre	atments				
There are no Acid Volume records to display.				There are no	Fracture Treatr	nents record	s to display.				
	Formation N	ame: VIRGII	LIAN		Code: 40	6VRGN	C	lass: COMM	DISP		
	Spacing	Orders				Perforated I	ntervals				
Orde	r No	Uı	nit Size		From To						
There are	e no Spacing C	Spacing Order records to display. 4024 4046									
					4534		54	108			
					6160)	65	548			
	Acid V	olumes		$\neg \sqcap$		Fracture Tre	atments				
There a	re no Acid Volu	ime records	to display.		There are no Fracture Treatments records to display.						
	Formation N	ame: MISSC	DURIAN		Code: 40	5MSRN	C	lass: COMM	DISP		
	Spacing	Orders				Perforated In	ntervals				
Orde	r No	Uı	nit Size		From		То				
There are	e no Spacing C	order records	to display.		7164	ļ.	72	299			
	Acid Ve	olumes				Fracture Tre	atments				
There a	re no Acid Volu	ime records	to display.		There are no	Fracture Treatr	ments record	s to display.			
ormation			lτ	ор			0.4				
	.N			•		/ere open hole l ate last log run:	-				

Formation	Тор
WOLFCAMPIAN	3550
VIRGILIAN	4000
MISSOURIAN	7160

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

November 20, 2019 2 of 3

OCC - OPERATOR SET A D-V TOOL AT 5,420' AND ALSO WAS PERFORATED AND SQUEEZED AT 4,590'. SEE 1002C FOR DETAILS. OCC - UIC PERMIT NUMBER 1813020029

FOR COMMISSION USE ONLY

1144109

Status: Accepted

November 20, 2019 3 of 3

Rev. 2009

PLEASE TYPE OR USE BLACK INK ONLY FORMATION RECORD


Give formation names and tops, if available, or descriptions and thickness of formations drilled through. Show intervals cored or drillstem tested.

NAMES OF FORMATIONS	TOP
WOLFCAMPIAN	3,550
VIRGILIAN	4000
MISSOURIAN	7,160
and the second s	
	\$
	i epe
	÷

LEASE NAME	SELBY SWD	WELL NO	1
	FOR COMMISSION U	SE ONLY	
ITD on file	Types TNO		

	FOR COMMISSION USE ONLY
APPROVED DISAPPR	DVED 2) Reject Codes
Were open hole logs run?	X yes no
and the second s	no 5/29/2019
Were open hole logs run? Date Last log was run Was CO ₂ encountered?	The state of the s

Other remarks: OCC - Operator set a D-V too	ol at 5420° and also was per-	forated
+ squeezed at 4590' see 1002	C for details	
DCC-111C permit # 181302	0029	



If more than three drainholes are proposed, attach a separate sheet indicating the necessary information.

Direction must be stated in degrees azimuth. Please note, the horizontal drainhole and its end point must be located within the boundaries of the lease or spacing unit.

Directional surveys are required for all drainholes and directional wells.

		640 /	Acres	 	
		*			

BOTTOM HOLE LOCATION FOR DIRECTIONAL HOLE

SEC	TWP	RGE		COUNTY			
Spot Loc	ation				Feet From 1/4 Sec Lines	FSL	FWL
Measure	1/4 d Total Depth	1/4	1/4 ue Vertical De		BHL From Lease, Unit, or Propo	erty Line:	
	· · · · · · · · · · · · · · · · · · ·				And the second s		

BOTTOM HOLE LOCATION FOR HORIZONTAL HOLE: (LATERALS)

SEC	TWP	RGE		COUNTY			
Spot Loc	cation 1/4	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Depth of	f , ,		Radius of Turn	1. Jan 1884 - 11. 11. 11. 11. 11. 11. 11. 11. 11. 1	Direction	Total Length	
		True Vertical De	pth	BHL From Lease, Unit, or Pro	operty Line:		

SEC	TWP	RGE		COUNTY			
Spot Loc	cation	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Depth of			Radius of Turn		Direction	Total	
Deviation	n		the section of the se		A COMMENT OF THE PROPERTY OF T	Length	
Measured Total Depth True Vertical De			pth	BHL From Lease, Unit, or Pr	roperty Line:		

SEC	TWP	RGE		COUNTY			
Spot Loc	ation	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Depth of Deviation		.,,,	Radius of Turn		Direction	Total Length	
Measured Total Depth True Vertical Dep				pth	BHL From Lease, Unit, or Pr	operty Line:	