

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35133253790000

Completion Report

Spud Date: March 05, 2022

OTC Prod. Unit No.: 133-024479

Drilling Finished Date: March 14, 2022

1st Prod Date: April 07, 2022

Completion Date: March 28, 2022

Drill Type: STRAIGHT HOLE

Well Name: EAST CROMWELL UNIT 1409

Purchaser/Measurer:

Location: SEMINOLE 3 10N 8E
S2 SW SE NE
165 FSL 1650 FWL of 1/4 SEC
Latitude: 35.370343 Longitude: -96.444614
Derrick Elevation: 874 Ground Elevation: 880

First Sales Date:

Operator: KELLY COOK OIL LLC 23197

2401 N HARRISON ST STE 500
SHAWNEE, OK 74804-3148

Completion Type	
X	Single Zone
	Multiple Zone
	Commingled

Location Exception	
Order No	
There are no Location Exception records to display.	

Increased Density	
Order No	
There are no Increased Density records to display.	

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	8 5/8	23	R-3	273		180	SURFACE
PRODUCTION	5 1/2	15.5	K-55	3505	300	100	2894

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 3505

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Apr 07, 2022	CROMWELL	10	38				PUMPING			100

Completion and Test Data by Producing Formation

Formation Name: CROMWELL

Code: 402CMWL

Class: OIL

Spacing Orders

Order No	Unit Size
60499	UNIT

Perforated Intervals

From	To
3372	3376
3392	3398
3430	3446
3456	3460

Acid Volumes

1,000 GALLONS

Fracture Treatments

35,000 POUNDS SAND, 800 BARRELS WATER

Formation	Top
CALVIN UP	1630
CALVIN MID	1689
CALVIN LOW	1838
BOOCH	3099
GILCREASE	3255
CROMWELL	3368

Were open hole logs run? Yes

Date last log run: March 15, 2022

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

There are no Other Remarks.

FOR COMMISSION USE ONLY

1148253

Status: Accepted