

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35045237510000

Completion Report

Spud Date: September 05, 2018

OTC Prod. Unit No.: 04522449100000

Drilling Finished Date: September 24, 2018

1st Prod Date: November 07, 2018

Completion Date: November 07, 2018

Drill Type: HORIZONTAL HOLE

Min Gas Allowable: Yes

Well Name: EAGLE EYE 3 AP 2HM

Purchaser/Measurer: MEWBOURNE MARKETING INC.

First Sales Date: 11/07/2018

Location: ELLIS 34 20N 26W
NW SW SE SE
415 FSL 1000 FEL of 1/4 SEC
Latitude: 36.160095 Longitude: -99.956657
Derrick Elevation: 2478 Ground Elevation: 2455

Operator: MEWBOURNE OIL COMPANY 6722
PO BOX 7698
3620 OLD BULLARD RD
TYLER, TX 75711-7698

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	696589		676837	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	13 3/8	48	J-55	780		490	SURFACE
INTERMEDIATE	7	29	P-110	8130		405	1800

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
LINER	4 1/2	13.5	HCP-110	6041	0	615	8019	14060

Total Depth: 14090

Packer		Plug	
Depth	Brand & Type	Depth	Plug Type
There are no Packer records to display.		There are no Plug records to display.	

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Dec 17, 2018	MARMATON	300	43.6	778	2593	169	FLOWING	1936	OPEN	230

Completion and Test Data by Producing Formation

Formation Name: MARMATON

Code: 404 MRMN

Class: OIL

Spacing Orders

Order No	Unit Size
585313	640

Perforated Intervals

From	To
9080	14060

Acid Volumes

20,000 GALS 15% NEFE HCL ACID

Fracture Treatments

FRACED WITH 3,380,900 GALS SLICK WATER CARRYING 4,000,000 LBS 30/50 WHITE SAND

Formation	Top
MARMATON	8730

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

There are no Other Remarks.

Lateral Holes

Sec: 3 TWP: 19N RGE: 26W County: ELLIS

SW SW SE SE

170 FSL 1316 FEL of 1/4 SEC

Depth of Deviation: 8214 Radius of Turn: 528 Direction: 181 Total Length: 4980

Measured Total Depth: 14090 True Vertical Depth: 8794 End Pt. Location From Release, Unit or Property Line: 170

FOR COMMISSION USE ONLY

1143588

Status: Accepted