

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35093252580000

Completion Report

Spud Date: August 18, 2021

OTC Prod. Unit No.: 09322748400000

Drilling Finished Date: September 12, 2021

1st Prod Date: November 15, 2021

Completion Date: October 05, 2021

Drill Type: HORIZONTAL HOLE

Well Name: SAVANNAH 1-24H

Purchaser/Measurer: MUSTANG GAS PRODUCTS

Location: MAJOR 25 20N 11W
NE NE NE NW
260 FNL 2425 FWL of 1/4 SEC
Latitude: 36.187582 Longitude: -98.326657
Derrick Elevation: 1203 Ground Elevation: 1180

First Sales Date: 11/15/2021

Operator: ROX EXPLORATION INC 18783

2416 PALMER CIRCLE
NORMAN, OK 73069-6301

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	722329		There are no Increased Density records to display.	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9-5/8	36	J55	505		250	SURFACE
INTERMEDIATE	7	26	P110	8243	2500	875	1500
PRODUCTION	4.5	13.5	P110	14080	2000	700	2891

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 14100

Packer		Plug	
Depth	Brand & Type	Depth	Plug Type
8550	ARROW SET 3	There are no Plug records to display.	

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Nov 15, 2021	HUNTON	140	39	534	3814	1700	PUMPING		open	190

Completion and Test Data by Producing Formation									
Formation Name: HUNTON				Code: 269HNTN			Class: OIL		
Spacing Orders				Perforated Intervals					
Order No		Unit Size		From			To		
719043		640		8767			13979		
Acid Volumes				Fracture Treatments					
172,518 GAL 15% HCL				105,829 BBLS WATER ; 5,622,272 LBS SAND					

Formation	Top
HUNTON	8450

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks
There are no Other Remarks.

Lateral Holes
Sec: 24 TWP: 20N RGE: 11W County: MAJOR NW NW NE NW 45 FNL 1322 FWL of 1/4 SEC Depth of Deviation: 7600 Radius of Turn: 685 Direction: 335 Total Length: 5610 Measured Total Depth: 14100 True Vertical Depth: 8275 End Pt. Location From Release, Unit or Property Line: 45

FOR COMMISSION USE ONLY
<div>Status: Accepted</div> <div>1147229</div>