Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000 Rule 165: 10-3-25

Completion Report

API No.: 35073261660001

OTC Prod. Unit No.: 073-224881

Amended

Amend Reason: OCC - CORRECTION

Drill Type: HORIZONTAL HOLE

Well Name: THREE BIRDS 19-08-16 1MH

Location: KINGFISHER 16 19N 8W N2 NW NW NW 210 FNL 330 FWL of 1/4 SEC Latitude: 36.12999036 Longitude: -98.06720694 Derrick Elevation: 1227 Ground Elevation: 1209

Operator: CHISHOLM OIL & GAS OPERATING LLC 23991

6100 S YALE AVE STE 1700 TULSA, OK 74136-1921 Spud Date: October 25, 2018 Drilling Finished Date: December 11, 2018 1st Prod Date: January 13, 2019 Completion Date: January 13, 2019

Min Gas Allowable: Yes

Purchaser/Measurer: KINGFISHER MIDSTREAM

First Sales Date: 01/16/2019

	Completion Type	Location Exception	Increased Density
Х	Single Zone	Order No	Order No
	Multiple Zone	694502	There are no Increased Density records to display.
	Commingled		

Casing and Cement											
т	Туре		Size	Weight	Grade	Grade Feet		PSI SAX		Top of CMT	
CONDUCTOR			20			80				SURFACE	
SURFACE			9 5/8	40	J-55	41	1			SURFACE	
PROD	UCTION		7	29	P-110	81	68		275	5010	
	Liner										
Туре	Size	Weig	ht	Grade	Length	PSI	SAX	SAX Top Depth Bott		Bottom Depth	
LINER	4 1/2	13.5	5	P-110	4822	0 0 7992					

Total Depth: 12814

Pac	cker	Plug				
Depth	Brand & Type	Depth	Plug Type			
8168 - 12814	SWELL PACKERS OPEN HOLE COMPLETION	There are no Plug records to display.				

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Feb 05, 2019	MISSISSIPPIAN (LESS CHESTER)			341	1722	722 1403 ESP			64/64	150
		Con	npletion and	Test Data k	by Producing F	ormation				
	Formation Name: MISSISSIPPIAN (LESS Code: 359MSNLC Class: OIL CHESTER)									
Spacing Orders				Perforated Intervals						
Order No Unit Size				From To			о			
686000 640				There are	no Perf. Interva					
Acid Volumes				Fracture Treatments						
47,333 GAL 15% HCL			7	729,711 LBS 100 MESH SAND; 4,086,584 LBS 30/50 SAND						
				12,413,341 GAL SLICKWATER						
			L							

Formation	Тор
CHECKERBOARD	6435
BIG LIME	6634
OSWEGO 3	6765
VERDIGRIS	6851
PINK LIME	6963
CHESTER	7170
MANNING	7297
MISSISSIPPIAN (LESS CHESTER)	7572
OSAGE	7618
OSAGE 4	7767
OSAGE 6 CHERT BENCH	7924
OSAGE 6B	7952

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

OCC – THIS IS AN OPEN HOLE COMPLETION FROM THE BOTTOM OF THE 7" AT 8168' TO TERMINUS AT 12814', THE 4 1/2 LINER IS NOT CEMENTED.

Lateral Holes					
Sec: 16 TWP: 19N RGE: 8W County: KINGFISHER					
SW SE SW SW					
176 FSL 848 FWL of 1/4 SEC					
Depth of Deviation: 7540 Radius of Turn: 403 Direction: 179 Total Length: 4640					
Measured Total Depth: 12814 True Vertical Depth: 7993 End Pt. Location From Release, Unit or Property Line: 176					

Status: Accepted