Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

OTC Prod. Unit No.: Drilling Finished Date: March 12, 2019

1st Prod Date:

First Sales Date:

Completion Date: March 25, 2019

Drill Type: STRAIGHT HOLE

SERVICE WELL

Well Name: FAY SWD 1-31 Purchaser/Measurer:

Location: BLAINE 31 16N 13W

NE NE NW NW 2447 FSL 1041 FWL of 1/4 SEC

Derrick Elevation: 0 Ground Elevation: 1775

Operator: NUERA DISPOSALS LLC 24166

PO BOX 131 204 E MAIN ST

WEATHERFORD, OK 73096-0131

Completion Type
Single Zone
Multiple Zone
Commingled

Location Exception
Order No
There are no Location Exception records to display.

Increased Density
Order No
There are no Increased Density records to display.

Casing and Cement								
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT	
SURFACE	9 5/8	36		504		250	SURFACE	
PRODUCTION	7	29	L-80	5663		1025	2950	

				Liner				
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 5696

Pac	ker
Depth	Brand & Type
2963	AS-1X

PI	ug
Depth	Plug Type
5623	CEMENT

Initial Test Data

May 09, 2019 1 of 2

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
			There are n	no Initial Data	a records to disp	olay.				
		Con	npletion and	Test Data k	y Producing F	ormation				
	Formation Name: WOL	FCAMPIAN		Code: 45	1WFMP	С	lass: COMM	DISP		
	Spacing Orders				Perforated In	ntervals		\neg		
Order	No	Unit Size		Fron	n	7	ō			
N/A	P			3624	1	4790				
	Acid Volumes		$\neg \vdash$		Fracture Tre	atments				
There are no Acid Volume records to display.				There are no Fracture Treatments records to display.						
	Formation Name: VIRO	BILIAN		Code: 40	6VRGN	C	lass: COMM	DISP		
	Spacing Orders				Perforated In	ntervals				
Order	No	Unit Size		Fron	n	7	ō	\neg		
N/A	P			4790)	51	50			
	Acid Volumes		\neg \vdash		Fracture Tre	atments				
There are no Acid Volume records to display.			$\neg \vdash$	There are no Fracture Treatments records to display.						

Formation	Тор
(BROWN DOLOMITE) TOP WOLFCAMPIAN	3610
VIRGILIAN	4790

Were open hole logs run? No

Date last log run: February 06, 2019

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

PERMIT NUMBER 1810290005 FIRST BOND LOG TOP 3,245' SQUEEZE 3,000' THROUGH PERFORATIONS SECOND BOND LOG TOP 2,695' TOP PERFORATIONS 3,624'

FOR COMMISSION USE ONLY

1142508

Status: Accepted

May 09, 2019 2 of 2

Justin Dudgeon

NAME (PRINT OR TYPE)

SIGNATURE

4/1/2019

DATE

(580) 530-1691

PHONE NUMBER

Form 1002A

Rev. 2009

PLEASE TYPE OR USE BLACK INK ONLY

FORMATION REI Give formation names and tops, if available, or descrip drilled through. Show intervals cored or drillstem teste	tions and thickness of formations	LEASE NAME	Fay SWD	WELL NO. 1-31
			50D 001MH	OCIONITICE ONLY
Brown Dolomite Town House	3,610		FOR COMMI	SSION USE ONLY
Brown Dolomite Top Wolfcampia	3,010	ITD on file YE	S NO	
·	4,370	APPROVED DIS	SAPPROVED 2) Rejec	t Codes
Virgilian	4790		2) Rejec	Codes
	9			
		Were open hole logs run?		
		Date Last log was run	2/6/2	2019
		Was CO ₂ encountered?	yes _X_no	at what depths?
		Was H₂S encountered?	yes _X_no	at what depths?
		Were unusual drilling circu	imstances encountered?	yes X no
		If yes, briefly explain below	V	-
Other remarks: Permit 1810290005				
First Bond Log Top 3245				
Squeeze 3000 thru perfs				
Second Bond- Top 2695				
Top Perfs 3624				
640 Acres	BOTTOM HOLE LOCATION FO	OR DIRECTIONAL HOLE		
	SEC TWP	RGE COUNTY		
	Spot Location		I	
		1/4 1/4 1/4 True Vertical Depth	Feet From 1/4 Sec Lines BHL From Lease, Unit, or Pro	FSL FWL
	inododrod rotal popul	True Vertical Deptil	Direction Lease, Onk, or Pro	porty Line.
	BOTTOM HOLE LOCATION FO	OR HORIZONTAL HOLE: (LATERAL	S)	
	LATERAL #1 SEC TWP	RGE COUNTY		
	Spot Location		T	
	1/4	1/4 1/4 1/4	Feet From 1/4 Sec Lines	FSL FWL
If more than three drainholes are proposed, attach a	Depth of Deviation	Radius of Turn	Direction	Total Length
separate sheet indicating the necessary information.	Measured Total Depth	True Vertical Depth	BHL From Lease, Unit, or Pro	perty Line:
Direction must be stated in degrees azimuth. Please note, the horizontal drainhole and its end				
point must be located within the boundaries of the lease or spacing unit.	LATERAL #2	RGE COUNTY		
Directional surveys are required for all		KGE COONTY		
drainholes and directional wells.		1/4 1/4 1/4	Feet From 1/4 Sec Lines	FSL FWL
640 Acres	Depth of Deviation	Radius of Turn	Direction	Total Length
	Measured Total Depth	True Vertical Depth	BHL From Lease, Unit, or Pro	
	LATERAL #3	0.05		
		RGE COUNTY		
	Spot Location 1/4	1/4 1/4 1/4	Feet From 1/4 Sec Lines	FSL FWL
	Depth of Deviation	Radius of Turn	Direction	Total
	Measured Total Depth	True Vertical Denth	BHI From Lease Unit or Pro	Length