## Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

OTC Prod. Unit No.: 07322591600000 Drilling Finished Date: June 25, 2019

1st Prod Date: August 05, 2019

Completion Date: August 05, 2019

Drill Type: HORIZONTAL HOLE

Well Name: HENNESSEY UNIT 1907 6LOH-33 Purchaser/Measurer: MUSTANG GAS PRODUCTS

Location: KINGFISHER 33 19N 7W

NE NW NE NW

230 FNL 1862 FWL of 1/4 SEC

Derrick Elevation: 1173 Ground Elevation: 1150

Operator: CHAPARRAL ENERGY LLC 16896

701 CEDAR LAKE BLVD

OKLAHOMA CITY, OK 73114-7800

	Completion Type							
X Single Zone								
		Multiple Zone						
Ī		Commingled						

Location Exception
Order No
There are no Location Exception records to display.

Increased Density
Order No
There are no Increased Density records to display.

First Sales Date: 08/08/2019

Casing and Cement								
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT	
SURFACE	9 5/8	36	J-55	485		198	SURFACE	
PRODUCTION	5 1/2	20	P-110	13070		1870	1520	

	Liner									
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth		
	There are no Liner records to display.									

Total Depth: 13085

Packer				
Depth	Brand & Type			
7282	FLOWCO ASIII			

Plug				
Depth	Plug Type			
There are no Plug records to display.				

	Initial Test Data									
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Sep 04, 2019	MISSISSIPPI SOLID	134	39.9	633	4724	243	FLOWING		N/A	108

November 05, 2019 1 of 2

## **Completion and Test Data by Producing Formation**

Formation Name: MISSISSIPPI SOLID

Code: 351MSSSD

Class: OIL

Spacing Orders					
Order No	Unit Size				
61811	UNIT				

Perforated Intervals				
From	То			
7925	12960			

Acid Volumes

NONE

Fracture Treatments	
219,242 BBLS TREATED FRAC WATER	
10,739,051# PROPPANT	

Formation	Тор
MISSISSIPPI SOLID	7925

Were open hole logs run? No Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

There are no Other Remarks.

## **Lateral Holes**

Sec: 33 TWP: 19N RGE: 7W County: KINGFISHER

SW SW SE SW

42 FSL 1528 FWL of 1/4 SEC

Depth of Deviation: 7275 Radius of Turn: 442 Direction: 182 Total Length: 5035

Measured Total Depth: 13085 True Vertical Depth: 7773 End Pt. Location From Release, Unit or Property Line: 42

## FOR COMMISSION USE ONLY

1143685

Status: Accepted

November 05, 2019 2 of 2