

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35051246580000

Completion Report

Spud Date: June 28, 2019

OTC Prod. Unit No.: 051-226860-0-0000

Drilling Finished Date: July 19, 2019

1st Prod Date: July 29, 2020

Completion Date: February 25, 2020

Drill Type: HORIZONTAL HOLE

Min Gas Allowable: Yes

Well Name: MCCLAIN 2-18-7XHW

Purchaser/Measurer: ENABLE MIDSTREAM

Location: GRADY 18 7N 5W
E2 SW SE NW
2310 FNL 1915 FWL of 1/4 SEC
Latitude: 35.081338 Longitude: -97.769789
Derrick Elevation: 1249 Ground Elevation: 1224

First Sales Date: 7/29/2020

Operator: CONTINENTAL RESOURCES INC 3186
PO BOX 268870
20 N BROADWAY AVE
OKLAHOMA CITY, OK 73126-8870

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	711864		696506	
	Commingled			696505	

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9.63	40	J-55	1492		460	SURFACE
PRODUCTION	5.5	23	P-100ICY	19303		2390	188

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 19335

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Jul 31, 2020	WOODFORD	312	45.48	564	1807	2869	FLOWING	948	40/64	590

Completion and Test Data by Producing Formation

Formation Name: WOODFORD		Code: 319WDFD		Class: OIL	
Spacing Orders		Perforated Intervals			
Order No	Unit Size	From	To		
621966	640	12250	14089		
711865	MULTIUNIT	14113	19146		
Acid Volumes		Fracture Treatments			
1519 BBLS 15% HCl		338,607 BBLS FLUID & 16,452,188 LBS OF SAND			

Formation	Top
WOODFORD	12250

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks
There are no Other Remarks.

Lateral Holes
Sec: 7 TWP: 7N RGE: 5W County: GRADY NW NW NE NW 50 FNL 1571 FWL of 1/4 SEC Depth of Deviation: 11619 Radius of Turn: 712 Direction: 360 Total Length: 7085 Measured Total Depth: 19335 True Vertical Depth: 11908 End Pt. Location From Release, Unit or Property Line: 50

FOR COMMISSION USE ONLY
<div>Status: Accepted</div> <div>1145474</div>