Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35019052210001 **Completion Report** Spud Date: May 01, 1952

OTC Prod. Unit No.: Drilling Finished Date: June 05, 1952

1st Prod Date:

Purchaser/Measurer:

First Sales Date:

Amended

Amend Reason: RECOMPLETE TO DEESE; SET PLUG

Completion Date: July 03, 1952

Recomplete Date: October 28, 2020

Drill Type: STRAIGHT HOLE

Well Name: SYCAMORE U. (T L CARPENTER 5A) 18-5A

CARTER 22 2S 3W E2 SE SW SW Location:

330 FSL 1015 FWL of 1/4 SEC Latitude: 34.362265 Longitude: -97.50624 Derrick Elevation: 0 Ground Elevation: 1014

Operator: CHAPARRAL ENERGY LLC 16896

> 4700 GAILLARDIA PKWY STE 200 **OKLAHOMA CITY, OK 73142-1839**

	Completion Type	
Х	Single Zone	
	Multiple Zone	Т
	Commingled	

	Location Exception										
	Order No										
	There are no Location Exception records to display.										

Increased Density				
Order No				
There are no Increased Density records to display.				

Casing and Cement										
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT			
SURFACE	10 3/4	40	H-40	178		175	SURFACE			
PRODUCTION	4 1/2	9.5	J-55	4385		675	2484			

Liner										
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth		
	There are no Liner records to display.									

Total Depth: 4750

Packer						
Depth	Brand & Type					
There are no Packer records to display.						

Plug						
Depth	Plug Type					
3936	CIBP					

Initial Test Data

April 02, 2021 1 of 2

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Nov 08, 2020	DEESE	1	34.9			1	PUMPING			
		Con	npletion and	Test Data b	y Producing F	ormation				
Formation Name: DEESE Code: 404DE						С	lass: OIL			
Spacing Orders Perforated Intervals										
Order No Unit Size From To										
97457 UNIT				2939)	39	004			
Acid Volumes Fracture Treatments										
4,700 GAL 15% HCL ACID				NONE						

Formation	Тор
DEESE	2936

Were open hole logs run? No Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks	
There are no Other Remarks.	

FOR COMMISSION USE ONLY

1146219

Status: Accepted

April 02, 2021 2 of 2