Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35139207670003 **Completion Report** Spud Date: August 14, 1975

OTC Prod. Unit No.: Drilling Finished Date: September 01, 1975

1st Prod Date:

First Sales Date:

Amended

Completion Date: September 01, 1975 Amend Reason: WELL REPAIR RAISED PACKER

Recomplete Date: February 26, 2018

Drill Type: STRAIGHT HOLE

SERVICE WELL

Well Name: BONRAY A SWD (BONRAY A 1) 1-D Purchaser/Measurer:

Location: TEXAS 31 4N 15E CM

C SE

1320 FSL 1320 FWL of 1/4 SEC Latitude: 36.76583 Longitude: -101.47914 Derrick Elevation: 3122 Ground Elevation: 3113

BKEP SERVICES LLC 22860 Operator:

6060 S AMERICAN PLAZA ST EAST STE 600

TULSA, OK 74135-4351

| Completion Type | | | | | | |
|-----------------|---------------|--|--|--|--|--|
| Χ | Single Zone | | | | | |
| | Multiple Zone | | | | | |
| | Commingled | | | | | |

| Location Exception | | | | | |
|---|--|--|--|--|--|
| Order No | | | | | |
| There are no Location Exception records to display. | | | | | |

| Increased Density | | | | | | |
|--|--|--|--|--|--|--|
| Order No | | | | | | |
| There are no Increased Density records to display. | | | | | | |

| Casing and Cement | | | | | | | | |
|-------------------|-------|--------|-------|------|------|-----|------------|--|
| Туре | Size | Weight | Grade | Feet | PSI | SAX | Top of CMT | |
| SURFACE | 8 5/8 | 24 | | 1633 | 1000 | | SURFACE | |
| PRODUCTION | 5 1/2 | 14 | | 5798 | 1000 | 80 | 3510 | |

| | | | | Liner | | | | | | |
|------|--|--------|-------|--------|-----|-----|-----------|--------------|--|--|
| Туре | Size | Weight | Grade | Length | PSI | SAX | Top Depth | Bottom Depth | | |
| | There are no Liner records to display. | | | | | | | | | |

Total Depth: 6785

| Packer | | | | | | |
|--------|---------------|--|--|--|--|--|
| Depth | Brand & Type | | | | | |
| 3921 | BAKER LOC-SET | | | | | |

| Plug | | | | | | |
|-------|-----------|--|--|--|--|--|
| Depth | Plug Type | | | | | |
| 4252 | CIBP | | | | | |
| 6150 | CIBP | | | | | |
| 6175 | CIBP | | | | | |

February 19, 2021 1 of 2

| | | | | Initial Tes | t Data | | | | | |
|--|----------------|----------------|----------------------|--|---|------------------|----------------------|---------------------------------|---------------|------------------------|
| Test Date | Formation | Oil BBL/Day | Oil-Gravity (API) | Gas MCF/Day | Gas-Oil Ratio Cu FT/BBL | Water BBL/Day | Pumpin or Flowing | Initial Shut- In Pressure | Choke Size | Flow Tubin Pressure |
| | l | 1 | There are | no Initial Data | records to disp | olay. | <u>I</u> | | | |
| | | Cor | npletion and | l Test Data b | y Producing F | ormation | | | | |
| Formation Name: TOPEKA | | | | Code: 406TOPK CI | | | lass: COMM | DISP | | |
| | Spacing Orders | | | | Perforated In | ntervals | | | | |
| Orde | er No U | nit Size | \neg \vdash | From | | То | | | | |
| There are no Spacing Order records to display. | | | | 3975 | | 4002 | | | | |
| | | | | 4054 | l . | 40 | 90 | | | |
| | Acid Volumes | | | | Fracture Tre | atments | | | | |
| There are no Acid Volume records to display. | | | | There are no Fracture Treatments records to display. | | | | | | |
| Formation | | Т | ор | D | /ere open hole l ate last log run: /ere unusual dri | | | untared? No | | |
| | | | | | xplanation: | illing circums | lances enco | antered? No | | |
| | | | | | | | | | | |

FOR COMMISSION USE ONLY

1139060

Status: Accepted

UIC ORDER NUMBER 547483

February 19, 2021 2 of 2

SIGNATURE

PLEASE TYPE OR USE BLACK INK ONLY FORMATION RECORD WELL NO. LEASE NAME Give formation names and tops, if available, or descriptions and thickness of formations drilled through. Show intervals cored or drillstem tested. FOR COMMISSION USE ONLY TOP NAMES OF FORMATIONS YES **□**N0 ITTO on file DISAPPROVED APPROVED 2) Reject Codes Were open hole logs run? ____yes ___ Date Last log was run yes ____no at what depths? Was CO₂ encountered? no at what depths? Was H₂S encountered? Were unusual drilling circumstances encountered? If yes, briefly explain below LIC ORDER 547483 Other remarks: BOTTOM HOLE LOCATION FOR DIRECTIONAL HOLE 640 Acres COUNTY SEC FWL Spot Location FSL Feet From 1/4 Sec Lines 1/4 Measured Total Depth BHL From Lease, Unit, or Property Line: BOTTOM HOLE LOCATION FOR HORIZONTAL HOLE: (LATERALS) LATERAL#1 COUNTY RGE Feet From 1/4 Sec Lines Spot Location FSL 1/4 Total Radius of Turn Deoth of Deviation Measured Total Depth BHL From Lease, Unit, or Prop True Vertical Depth separate sheet indicating the necessary information. Direction must be stated in degrees azimuth.
Please note, the horizontal drainhole and its end LATERAL #2 SEC | TWP point must be located within the boundaries of the IRGE lease or spacing unit. Directional surveys are required for all Spot Location FSL FWL Feet From 1/4 Sec Lines 1/4 1/4 drainholes and directional wells. Total Radius of Turn Depth of 640 Acres Length BHL From Lease, Unit, or Property Line Deviation Measured Total Depth

True Vertical Depth

Radius of Turn

True Vertical Depth

RGE

COUNTY

1/4 Feet From 1/4 Sec Lines

Length BHL From Lease, Unit, or Property Line

FSL

Total

FWL

LATERAL #3

Depth of

1/4

Deviation Measured Total Depth